RECEIVING AND ESTIMATING REPORT

CUST NO:020626 C.O.D

COMMENTS

TIAL	CUSTOMER ORDER NO.
JM	

TE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
8/21/91	08/23/91	BZ 1-75	6829623	700 22-250 BDL	R 91-16576

CESSORIES W/STUDS SCOPE BASE
L/REAR SIGHT

:OM:
BIG JOHN'S GUNS & SUPPLIES
1508 HOUSTON
NEDERLAND TX 77627
USA

SHIP TO:
BIG JOHN'S GUNS & SUPPLIES
1508 HOUSTON
NEDERLAND TX
USA 77627

COUNT NUMBER	ACCOUNT NUMBER N/C		PROM. DATE	ESTIMATED	VIA
		WRITE ☐ CLEAN/TEST			UPS

AIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

UN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

STOMER'S REQUEST Fires when closing bolt also, complaining of headspace problem

IN FAULT Cannot duplicate fire on closing complaint. However, trigger assembly has been improperly adjusted outside factory, as evidenced by non-Remington sealant on adjustment screw — 1) insufficient overtravel 2) insufficient sear-engagement. Trigger pull 4½ lbs. sear-lift .0075".

RTS

1.) Check for headspace

2.) Send repair quote for new trigger assembly at ½ normal cost, as gesture of good-will

REPAIRMAN HB	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90