REPAIR AND ESTIMATING REPORT

CUST NO:049349 C.O.D

AL | CUSTOMER ORDER NO.
M

COMMENTS

RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
/12/91	09/18/91	KW 5-72	6552407	700 270 BDL	R 91-18387

ESSORIES W/STUDS W/SWIVELS SCOPE BASE L/SIGHTS

OM:
CLARK, JIM
RT 2 BOX 111
FREINDSHIP RD
AMITE LA 70422
USA

SHIP TO:
CLARK, JIM
RT 2 BOX 111
FREINDSHIP RD
AMITE LA
USA 70422

OUNT NUMBER	ACCOUNT NUMBER N/C		PROM. DATE	ESTIMATED	VIA
		WRITE ☐ CLEAN/TEST		10-7-91	UPS

IR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

N CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

TOMER'S REQUEST "My Remington 700 went off when I chambered a round."

N FAULT Cannot make with malfunction in any way. However, trigger assembly has been adjusted outside factory — Trigger pull measures 2 lbs, below minimum specifications. Sealant is missing from all 5 adjustment screws. Sear left .008"

TS Based on attached letter, customer would prefer a non-cost lock safety. As a gesture of good-will, offer a new style trigger assembly at ½ normal cost.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
DE					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90