RECEIVING AND ESTIMATING REPORT

COMMENTS: DEL NOT OF OUR OFFER LEAVE OR GLASS SCREWS

INITIAL	CUSTOMER ORDER NO.	DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE			ORDER
HB		06/20/91	06/24/91		6234123	700	223	ARMY	R 91-1103

ACCESSORIES: L/WOOD SCOPE BASE

FROM:
CLINTON RIVER GUN SERVICE
30016 S RIVER RD
MT. CLEMENS MI 48045

SHIP TO:
CLINTON RIVER GUN SERVICE
30016 S RIVER RD
MT. CLEMENS MI 48045

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST: Repair "Firearm discharges when taking safety off"

MAIN FAULT: Trigger assembly tampered with and improperly adjusted outside factory, as evidenced by foreign, yellow sealant — 1) insufficient sear-engagement (as received, firing pin should sometimes not cock) 2) trigger pull as received ≈ 1 pound — trigger retraction not positive because of excessively light pull weights

PARTS

Offer replacement trigger assembly at nominal cost, as gesture of good-will

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
HB					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 7/90