RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 92-06062

INITIAL	CUSTOMER ORDER NO.
JJM	038326

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
02/18/92	02/26/92	BC 1-82	B6370740		700 243 RDL

ACCESSORIES W/STUDS SCOPE BASE L/REAR SIGHT

FROM:
FLOYDS SPORTING GOODS
4359 MERLE HAY RD
DES MOINES IA 50310

SHIP TO:
FLOYDS SPORTING GOODS
4359 MERLE HAY RD
DES MOINES IA 50310

CUST NO:001731 ILION

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		CLEAN/TEST		3-16	UPS

GUN CONDITION
- [ ] NEW
- [ ] LIGHTLY WORN
- [ ] WORN
- [ ] VERY WORN
- [ ] UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	fired on bolt closing				
TRIGGER GROUP		B2		✓	E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Rifle can be made to fire off of bolt as closed briskly. Disassembly of rifle reveals that trigger assembly has been improperly adjusted during factory assembly. Is missing from all adjustment screws.
1) trigger pull measured 1½ pounds (well below our minimum specification)
2) sear engagement is insufficient
Trigger pull 1½ pounds; sear-lift .011"

PARTS

COMMENTS
Offer new trigger assembly at ½ normal cost as a gesture of customer good-will

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
BWT					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/91