RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R91-25955

INITIAL	CUSTOMER ORDER NO.
LCS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
12/10/91	12/12/91	KI 5-88	C6250545		700 30-06 ADL/LS

ACCESSORIES W/STUDS

FROM:
GREAT GUNS INC OF TYLER TEXAS
5729 HWY 31 WEST
TYLER TX 75709
USA

SHIP TO:
GREAT GUNS INC OF TYLER TEXAS
5729 HWY 31 WEST
TYLER TX
USA 75709

CUST NO: 009222 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PPOM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST			UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.					E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

gun fires when bolt is closed

MAIN FAULT As received, sear-safety cam was stuck to sideplate of trigger assembly housing. When bolt was inserted and closed, firing pin simply followed-down on striking cam. Trigger assembly is contaminated with sticky, gummy residue — trigger assembly not functioning properly. Trigger pull measured to be 4.5 pounds; sear-lift — .014"

PARTS

COMMENTS Offer to clean present trigger assembly if possible. If not possible, offer replacement assembly at ½ normal cost, as a gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/91