RECEIVING AND ESTIMATING REPORT

BARBER - Kinzer PPS GAL RE0002272

COMMENTS: L/FLOOR PLATE, SCREWS W/BOTTOM OF SCOPE MOUNTS

ORDER: R 92-02977

INITIAL	CUSTOMER ORDER NO.
FPS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
01/16/92	01/24/92	BB 1-81	B6284415		700 270 WIN

ACCESSORIES: L/MAG BOX L/WOOD L/FOLLOWER L/MAG SPRING SCOPE BASE L/SIGHTS

FROM:
HAYNES, BILL
2804 PINEY PLAINS RD
CARY NC 27511

SHIP TO:
HAYNES, BILL
2804 PINEY PLAINS RD
CARY NC 27511

CUST NO:056875 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
C63103		☐ CLEAN/TEST		1/24/92	V4686959

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP						
BOLT ASSY.						
BARREL ASSY.						
REC. ASSY.						
WOOD			C1		E5	
METAL			C2			

"My 700 after loading occasionally will not cycle and must be re-cocked again before firing. Also occasionally after loading & open the safety switch is pushed to the "F" position the rifle has fired without pulling the trigger".

MAIN FAULT: Trigger has been improperly adjusted outside of factory. 1) sear-engagement is insufficient 2) over-travel is insufficient. 3) trigger pull is below our minimum spec.

Trigger pull 2½ pounds; sear-lift .010"

PARTS

COMMENTS: Offer new trigger assembly at ½ normal cost as a good will gesture

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
RRB					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/9