RECEIVING AND ESTIMATING REPORT

COMMENTS: BOTTOM HALF OF SEE THRU MTS ONLY

ORDER: R 92-05705

INITIAL	CUSTOMER ORDER NO.
JJM	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
02/14/92	02/20/92	DR 9-68	366828		700 308 BDL

ACCESSORIES: W/STUDS

FROM:
KERSCHNER, BRAD J
205 JEFFERSON ST
SCHUYLKILL HAVEN PA 17972

SHIP TO:
KERSCHNER, BRAD J
205 JEFFERSON ST.
SCHUYLKILL HAVEN PA 17972

CUST NO:058422 CJO.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
02		CLEAN/TEST			UPS

GUN CONDITION
- [ ] NEW
- [ ] LIGHTLY WORN
- [ ] WORN
- [ ] VERY WORN
- [ ] UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4	C1			
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

"... customer who said that while unloading the gun it fired while the bolt was being withdrawn (at about the middle of its length of travel)

MAIN FAULT: It is not possible for a Model 700 rifle to fire when the bolt is being moved rearward after opening, due to the design.
Examination of the fully and trigger assembly could not produce a malfunction of any sort. However, disassembly of the rifle revealed the trigger assembly has been improperly adjusted outside the following – 1) trigger pull was measured to be 2½ pounds (below our minimum spec) 2) over-travel excessive. Nevertheless, the rifle did not malfunction.

PARTS	COMMENTS
	Offer to clean and re-set present trigger assembly, or we can install a new trigger assembly at ½ normal cost, as a gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/9