RECEIVING AND ESTIMATING REPORT

COMMENTS: ATTN J STEKL

ORDER: R91-24429

INITIAL	CUSTOMER ORDER NO.	DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
JJM		11/22/91	11/27/91	BD 1-83	7600607		7 243

ACCESSORIES: W/STUDS SCOPE BASE L/SIGHTS

FROM:
RUD, DELBERT
P O BOX 212
DILWORTH MN 56529
USA

SHIP TO:
RUD, DELBERT
P O BOX 212
DILWORTH MN
USA 56529

CUST NO:053736 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

Rifle fired when safety was moved to "fire" position

MAIN FAULT: Cannot duplicate complaint. However, disassembly of rifle revealed bottom of frame and action dripping wet with oil. Trigger assembly has been adjusted outside factory – 1) Trigger pull measured at 2 pounds (well below minimum spec) trigger retraction is not positive 2) over-travel insufficient. The excessive oil, non-positive trigger retraction coupled with cold temperatures could conceivably cause a problem. Sear-lift "OK".

PARTS

COMMENTS: re-adjust and clean present trigger assembly, if possible. Or we can offer a new trigger assembly at frame cost, as a gesture of good-will, if it will better restore confidence in the rifle.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 8/91