RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 91-25205

INITIAL	CUSTOMER ORDER NO.
LCS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
12/04/91	12/06/91	WD 8-83	B6487829		700 30-06 BDL

ACCESSORIES W/STUDS SCOPE BASE

FROM:

THOMAS, JEFF
1911 GLENWAY AVE
COVINGTON KY 41014
USA

SHIP TO:

THOMAS, JEFF
1911 GLENWAY AVE
COVINGTON KY
USA 41014

CUST NO:054217 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

Delay in firing after trigger was pulled.

MAIN FAULT Could not duplicate complaint. However, disassembly of rifle revealed wrong of trigger assembly is contaminated with sticky substance, inhibiting proper movement of sear-safety cam post. Trigger assembly still plating in cold temperature, this could conceivably cause a delay in firing pin drop.

Triggers pull 4 3/4 pounds; sear-lift .014"

PARTS

COMMENTS Clean present trigger assembly if possible. If not, offer replacement assembly at $5 normal cost, as a gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN

GALLERY TESTER	DATE	DATE	DATE	DATE	DATE