RECEIVING AND ESTIMATING REPORT

ORDER R91-25098

INITIAL	CUSTOMER ORDER NO.	COMMENTS
LCS		L/FLOOR PLATE, SCREWS

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
12/03/91	12/05/91	DX 9-73	6671711		700 243 WIN

ACCESSORIES: L/WOOD L/FOLLOWER L/MAG SPRING L/SIGHTS

FROM:
WORLD TRADE TRANSPORT CORP
OF VA
22 EXPORT DRIVE
STERLING VA 22170
USA

CUST NO:054141 C.O.D

SHIP TO:
WORLD TRADE TRANSPORT CORP
OF VA
22 EXPORT DRIVE
STERLING VA
USA 22170

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1					
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.					E2	
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

1.) Rifle fired upon moving safety off
2) Bolt handle bent broken off indication of high pressure load

MAIN FAULT 1.) Trigger assembly has been improperly adjusted outside factory specs. a.) excessive over-travel b.) excessive sear engagement - cannot duplicate complaint however
2) bolt handle broken off with apparent high-pressure handload.

PARTS

COMMENTS 1) replace bolt - standard charge
2) offer to pay trigger assembly replacement as gesture of good-will.

Note ⇒ Per attached letter call Jack Moore with quotation price (703) 450-6800

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTER
B.W					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/