


these adjustments had been tampered with after the rifle left our factory, as the sealant on the screws was not original. In future use, we strongly advise that the trigger not be adjusted by un-trained non-Remington personnel.

Since we found the trigger assembly to be outside our specifications, we can either properly re-adjust the present assembly or, if it will restore your confidence in the rifle, we will install a new trigger assembly at no-charge as a gesture of good-will (either option subject to a \$10.00 handling and return shipping fee). We will await your decision and reply.

Thank you for affording us the opportunity to examine your rifle and report our findings.

Sincerely,

  
J.A. Stekl, Specialist  
Product Service

JAS:tpg

*Remington Arms Company, Inc.*