point, as shown by the attachment screw marks on the sides of the trigger finger-piece. Accidental contact with the wide trigger shoe, extending out beyond the sides of the trigger guard, upon bolt closing may have caused our customer's problem.

Since we found the firearm to function properly in every respect, we are prepared to return it to you in its present condition (after re-sealing the adjustment screws). However, if our customer desires, we will install a new trigger assembly at no-charge as a good-will gesture (either option subject to a \$10.00 handling and return shipping fee). We will await the decision and reply.

Thank you for affording us the opportunity to examine the rifle and report our findings.

Sincerely,

Í.A. Stekl, Specialist

Product Service

JAS: tpp