

RECEIVING AND ESTIMATING REPORT

Service Dept

1. Check barrel see if it will group
2. safety need to be changed goes off when open bolt
3. put in extractor can bolt its getting old

IN BDL/MAG R ORDER 90-30845

SHIP TO:

MEDENWOLD, KM
RR 1
HANKINSON

ND
58041

ST PROM. DATE ESTIMATED 12-17-90 VIA V45672957

UPS PARCEL POST TOTAL

VERY WORN ☐ MISUSED ☐ MARRED ☐

be changed Goes off
check B3L see if it

KM Medenwold
RRI
Hankinson N. Dak

701-242-7934
Easy to take, easy to tolerate.

PCE

erythromycin particles in tablets

Abbott Laboratories North Chicago, Illinois 60064

upper assembly and safety function
has been improperly adjusted
and the bolt is full and
not removed and not replaced

Key test up for accuracy

You to either properly re-adjust the
safety trigger assembly or, if you to
replace trigger assembly at a normal
price as a gesture of good-will, if it
will better re-stab confidence in the
up.

REPAIRMAN RBI	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6725 REV. 7/9

PPS 03395