

5/2/50

COMMENTS

L/REAR SIGHT

SHIP TO:

SC
29624

WRITE ☐ TARP

CUSTOMER'S REQUEST Various malfunctions (see attached letter copy)

AIN FAULT *tugger assembly is sucked from under on cause - internal
tugger parts are not moving properly - as received tugger
assembly not functional.*

REPAIRMAN 122	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

REV. 7/90

PPS 04357