

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-14520

INITIAL CUSTOMER ORDER NO.

FPS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

04/28/94

04/28/94

A6471639

700

BMM MAG

BDL

ACCESSORIES

W/STUDS

FROM:

SHIP TO:

AAA ACE BUYERS
823 B HWY. 99N
EUGENE

OR 97402

AAA ACE BUYERS
823 B HWY. 99N
EUGENEOR
97402

CUST NO: 096689 C.I.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER W/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE 20.
EXCISE
TAX
INSURANCE
UPS 8.0
PARCEL POST
TOTAL 28.0

*Expedite per C. Mocko**5/5/94*

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

Safety is defective sometimes it fires when the safety is disengaged

MAIN FAULT

Trigger pull and trigger guard screw have been adjusted outside of the factory. Remington does not recommend that the trigger adjusting screw be adjusted outside of the factory. Exchange trigger Assy at a very low price, strictly as a gesture of good will and to restore customer's confidence in rifle. FRONT GUARD SCREW does not tighten properly exchange N/C

PARTS

COMMENTS

*Front guard screw**Trigger pull measured 2 LBS
Rec'd and sent left was .010*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PAT

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 RE

PS00247