

RECEIVING AND ESTIMATING REPORT 1/

COMMENTS

TIAL	CUSTOMER ORDER NO.						
IVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE		ORDER	
B/91	01/28/91	AZ 3-75	6846400	700	30-06 BDL	R 91-02777	
CESSORIES	W/STUDS		SCOPE BASE				

OM:

CAMPBELL, WILLIAM L
HC 66 BOX 266B
FERRIDAY

LA 71334

SHIP TO:

CAMPBELL, WILLIAM L
HC 66 BOX 266B
FERRIDAY

LA 71334

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	FROM DATE	ESTIMATED	VIA
					2-8-91	UPS

AIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
------------	-----	-----------	-----	-------------	-------

IN CONDITION:

☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

STOMER'S REQUEST

Gun fired when Bolt was closed.

Trigger assembly contaminated with sticky, gummy residue. Trigger parts are gummed and not moving properly. Semi-auto gun stuck to catch plate or trigger housing. Bolt release is sticking and not operating properly. Check if trigger assembly and return of action wet with excessive oil(?)

Send quotation to clean present trigger assembly, if possible. If not possible, we can install a new trigger assembly at 1/2 normal cost, as a gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90