

| | | | | | | | | |
|--|--------------------|------------|---------------|-------------------|-----------------|---------------------------|--|--|
| RECEIVING AND ESTIMATING REPORT | | | COMMENTS | | | ORDER R92-27011 | | |
| INITIAL | CUSTOMER ORDER NO. | | | | | | | |
| FPS | | | | | | | | |
| DATE RECEIVED | DATE OPENED | DATE CODE | SERIAL NUMBER | NEW SERIAL NUMBER | MODEL AND GRADE | | | |
| 12/05/92 | 12/10/92 | CU 4-71 | 6435318 | | 700 6MM REM ADL | | | |
| ACCESSORIES | | SCOPE BASE | | | | | | |
| W/STUDS | | | | | | | | |

| | |
|--|--|
| FROM: | SHIP TO: |
| DICK'S GUN REPAIR SHOP 175 LIBERTY SPG RD SUFFOLK VA 23434 | DICK'S GUN REPAIR SHOP 175 LIBERTY SPG RD SUFFOLK VA 23434 |

| | | | | | | | | | | | |
|--|--|--------------------|--|----------------------|--|------------|--|-----------|--|---------------|--|
| ACCOUNT NUMBER | | ACCOUNT NUMBER N/C | | CUST NO:007011 ILIDN | | PROM. DATE | | ESTIMATED | | VIA | |
| WRITE <input type="checkbox"/> CLEAN/TEST | | | | | | | | | | UPS | |
| GUN CONDITION | | | | | | | | | | REPAIR CHARGE | |
| <input type="checkbox"/> NEW <input type="checkbox"/> LIGHTLY WORN <input type="checkbox"/> WORN <input type="checkbox"/> VERY WORN <input type="checkbox"/> UNREPAIRABLE <input type="checkbox"/> MARRED | | | | | | | | | | EXCISE | |
| | | | | | | | | | | TAX | |
| | | | | | | | | | | INSURANCE | |
| | | | | | | | | | | UPS | |
| | | | | | | | | | | PARCEL POST | |
| | | | | | | | | | | TOTAL | |

| CUSTOMER CONCERN | AMMO | FUNCTION | FINISH | ACCURACY | FIT | INSPECT |
|------------------|------|----------|--------|----------|-----|---------|
| CYCLE | A1 | | | | | |
| TRIGGER GROUP | | | | | E1 | F1 |
| BOLT ASSY. | | | | | | |
| BARREL ASSY. | | | | D1 | F3 | F4 |
| REC. ASSY. | | | | D2 | E4 | F4 |
| WOOD | | | C1 | D3 | E5 | F5 |
| METAL | | | C2 | | | |

MAIN FAULT *Unable to duplicate Complaint. However, it was noted that the trigger assembly had been adjusted outside the factory (no force on front of connector) and trigger pull below factory specifications*
Trigger Pull 1 1/4 pounds, 5000 ft. sec. Gun condition good, brown residue found on bolt stop release. rifle mfg 1971

| | | | | | |
|--|-------|-------------------------------------|-------------------------------------|--------|---------|
| COMMENTS | | | | | |
| <i>Based on condition of trigger assembly and the fact that the rear engagement has tampered with, offer a new trigger assembly at 1/2 normal cost; is a gesture of good will.</i> | | | | | |
| REPAIRMAN | PROOF | CLEAN | TEST | TARGET | PATTERN |
| <i>JR</i> | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | | |
| GALLERY TESTER | DATE | DATE | DATE | DATE | DATE |
| | | | | | |