Remington.

TRACKING DOCUMENT

Repair Order Number



Repair Order Number

RE00073979 Account # - R- Description/Serial Number

7685074

Model 7 Center Fire Caliber: 7 MM 08

Repairman -

Robert Frink

Date Received · 12/15/2003

Estimate Date -

Current Date - 12/17/2003

Customer

EARL DILLON 211 LAVENDER ST Return To

EARL DILLON 211 LAVENDER ST

OAK HILL. WV 25901 US

OAK HILL, WV 25901 US

Phone (H) Phone (W) (304)-465-1645

Fax Email

M123

M992

FORWARD TO PRODUCT SERVICE

N

FOR INSPECTION DELAYED FIRING

M123

Problems

FORWARD TO PRODUCT SERVICE FOR

Material #	<u>MaterialDesc</u>	Quantity	<u>Quantity</u>	Quantity	<u>Warranty</u>
	•	Needed	From Inv	From Kit	(Y/N)
Part					
F92458	7 TRIGGER ASSB	1	1	0	N
F97422	7 STOCK YOUTH (VENDOR)	1	1	0	N
Part	Total:	2	2	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	N
4000119	GR-TEST	1	1	0	Y
Service	Total:	1	1		

Condition Customer requests having stock refinished. At present we are not refinishing wood. We will supply a new stock at our cost. **ProblemNotes** Upon receipt we could not duplicate the reported concern. Trigger asembly components covered with a heavy brown sticky substance. Poor maintenance. Replace trigger assembly at 1/2 MSP. Proof Clean Test Pattern Repairman Target Gallery Tester Date Date Date Date Date