

# RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL	CUSTOMER ORDER NO.					
LCS	3818					
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE		ORDER
10/02/90	10/10/90	KH 0-07	B6062048	700	270	BDL R 90-26260
ACCESSORIES						
W/STUDS		L/SIGHTS				

FROM:	SHIP TO:
EWELL CROSS GUN SHOP P.O. BOX 3025 8240 I-30 WEST FT WORTH TX 76108	EWELL CROSS GUN SHOP P.O. BOX 3025 8240 I-30 WEST FT WORTH TX 76108

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
						UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION:

☐ NEW
 ☒ SLIGHTLY WORN
 ☐ VERY WORN
 ☐ MISUSED
 ☐ MARRED

CUSTOMER'S REQUEST

"The gun fired when the safety was pushed off"

MAIN FAULT: Entire trigger assembly is contaminated with a sticky residue (appears to be dried WD-40). The rear safety cam is stuck solidly to the side plate of the trigger assembly and is inoperative. Rifle has not been properly maintained.

PARTS: Send quotation to replace trigger assembly at normal price, as shown of good will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE