

BV = 1/79

Settled 6/25/01
Repair AS listed below
FLS 6/28/01

April 12, 2001

Dennis Sanita
Manager Consumer Affairs
Remington Arms Company, Inc.
14 Hoefler Avenue
Ilion, NY 13357

Dear Dennis,

Enclosed please find the 270 that we talked about that was involved in the accident. I am sorry that it has taken us so long to get it to you.

You said when I talked to you that you would check it for any defects and put a new stock on it. We don't know if it is defective, all we know is that no one was touching it and we thought the safety was on when it misfired.

Please call my wife at her work # listed below upon receipt of the gun so that we know you received it. If you have any more questions about the accident you can talk to her.

Her work # is 800-776-9362-ext. 2268

Thank you in advance for your help.

Dennis Gregory
705 N Street
Gering, NE 69341
(308)436-4759

*Did not do
not aware
of PL
when this
was written*

As Received - could not duplicate
concern - TA coated with heavy
sticky residue - Install new
TA at M/C - Install new
stock M/C

Charge 230145
FLS 4/17/01

Please Expedite per DJS.

BV = 1/79

Serial Number: **A6694508**

Model: **700**



RE00026320

April 12, 2001

Dennis Sanita
Manager Consumer Affairs
Remington Arms Company, Inc.
14 Hoefler Avenue
Ilion, NY 13357

Dear Dennis,

Enclosed please find the 270 that we talked about that was involved in the accident. I am sorry that it has taken us so long to get it to you.

You said when I talked to you that you would check it for any defects and put a new stock on it. We don't know if it is defective, all we know is that no one was touching it and we thought the safety was on when it misfired.

Please call my wife at her work # listed below upon receipt of the gun so that we know you received it. If you have any more questions about the accident you can talk to her.

Her work # is 800-776-9362-ext. 2268

Thank you in advance for your help.

Dennis Gregory
705 N Street
Gering, NE 69341
(308)436-4759

As Received - could not duplicate
concern - TA coated with heavy
sticky residue - Install new
TA at M/C - Install new
stock M/C

Charge 230145
FLS 4/17/01