

RECEIVING AND ESTIMATING REPORT

| | | | | | |
|-----------------------|--------------------|------------|---------------|-----------------|------------|
| CUST NO: 051081 C.O.D | | COMMENTS | | STEKO | |
| TIAL | CUSTOMER ORDER NO. | | | | |
| DATE RECEIVED | DATE OPENED | DATE CODE | SERIAL NUMBER | MODEL AND GRADE | ORDER |
| 9/11/91 | 10/15/91 | PY 6-74 | 6763773 | 700 270 WIN ADL | R 91-20765 |
| ACCESSORIES | W/STUDS | SCOPE BASE | L/SIGHTS | | |

| | |
|--|--|
| FROM: | SHIP TO: |
| KOMES, DAVE RR 1 BOX 82 A HINCKLEY USA | KOMES, DAVE RR 1 BOX 82 A HINCKLEY USA |
| IL 60520 | IL 60520 |

| | | | | | | |
|--------------|--------------------|--------------------------------|------------|------------|-----------|-----|
| COUNT NUMBER | ACCOUNT NUMBER N/C | WRITE <input type="checkbox"/> | CLEAN/TEST | PROM. DATE | ESTIMATED | VIA |
| | | | | | 10/22/91 | UPS |

| | | | | | |
|-------------|-----|-----------|-----|-------------|-------|
| PAIR CHARGE | TAX | INSURANCE | UPS | PARCEL POST | TOTAL |
| | | | | | |

UN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

"Refl. exchanges when attempting to unload"

MAIN FAULT: No fault found in operation of rifle. However, disassembly would show action (including trigger assembly) is very dirty and oily. Inside of trigger assembly is also contaminated with excess oil and dirt. Refl. has been epoxy bedded and otherwise altered outside factory. Trigger pull - 5 pounds; Sear lift .007"

Clean present trigger assembly, if possible. If not, quote new trigger assembly at 1/2 normal cost, as a gesture of good-will.

| | | | | | |
|----------------|-------|-------|------|--------|---------|
| REPAIRMAN | PROOF | CLEAN | TEST | TARGET | PATTERN |
| L. J. 22 | | | | | |
| GALLERY TESTER | DATE | DATE | DATE | DATE | DATE |
| | | | | | |

OFFICE COPY

RD6925 REV. 7/90

PS03736