

## **TRACKING DOCUMENT**

Carl Cotton

Quantity

From Kit

1

1

1

0

1

1

23

20

0

0

0

0

0

0

0

0

li de terre

**Warranty** 

(Y/N)

Y

Y

Υ

Ν

Y

Y

## **Repair Order Number Repair Order Number Description/Serial Number** Repairman -RE00074235 6574429 **Date Received** • 1/14/2004 Account # - R-Model 700 Center Fire Caliber: 243 ADL Estimate Date - 1/5/2004 Current Date - 1/21/2004 Customer **Return To** SHEILA MC CRADY SHEILA MC CRADY ROUTE 1 BOX 134A ROUTE 1 BOX 134A ROCKPORT. WV 26169 US ROCKPORT, WV 26169 US Phone (H) (304)-482-3231 Fax Phone (W) Email Problems Reported ROUNDER M123 FORWARD TO PRODUCT SERVICE M122 RUSTED COMPONENT TRIG ADJ SCREWS RESET, CANNOT FOR INSPECTION M178 REPLACE TRIGGER ASSEMBLY M993 FIRES WHEN TAKEN OFF SAFE M239 Repair Material # MaterialDesc Quantity Quantity From Inv Needed Part F26345 700 TRIG ASSB RH 1 Part Total: 1 Service 4000294 **GR-CHECK TPA** 1 4000104 ARMS SERV SHIPPING & HANDLING 0 4000116 **GR-LABOR** 20 4000118 **GR-CLEAN** 1 4000119 **GR-TEST** 1 Service Total: 23

Condition dirty Could not duplicate customer's complaint. The act. and trigger assy. are covered with dirt and rust, ProblemNotes very poorly maintained. Quoted for cleaning and replacing trigger assy, under the bolt lock safety modification program. Repairman Proof Clean Test Pattern Target Gallery Tester Date Date Date Date Date

## PS04153