

RECEIVING AND ESTIMATING REPORT

COMMENTS
W/BTH OF SEE THRU SCOPE MOUNT

INITIAL FPS	CUSTOMER ORDER NO.		DATE RECEIVED 01/10/91		DATE OPENED 01/16/91	DATE CODE	SERIAL NUMBER B4210700	MODEL AND GRADE 700 30-06 BDL	ORDER R 91-01625
ACCESSORIES W/STUDS			KA 5-80 2ND TIME IN						

FROM:

**REIMER, ROBERT
249 MAIN ST
SLATINGTON**

PA 18000

SHIP TO:

**REIMER, ROBERT
249 MAIN ST
SLATINGTON**

**PA
18000**

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 1-24-91	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------------------------	-------------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARTS FEE	TOTAL
---------------	-----	-----------	-----	-----------	-------

GUN CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☒ MISFIRE

CUSTOMER'S REQUEST

*Firing pin didn't hit primer,
when opening Bolt. Gun
Gun (unsafe) to use.*

MAIN FAULT

*Cannot duplicate above complaint. Try
operate normally. Try pull the trigger left
hand firing pin assembly one drop and with
The expensive lubrication in the gun
weather, could explain the problem.*