Remington Arms Co., Inc. Product Service Legal Case #:4464

Case Information

RE# **Date Opened** Date Opened(PS) **Incident Date** Pre Lit Obsolete **Date Closed** Lit

3/25/2010 4/1/2010 4/1/2010 192755

Customer Information

Type **Business** First Name Last Name Street City Zip Age Contact H 304-364-2270 Incident John Cox 104 Walnut Hill Ln Gassaway 26624 E jcox3546@gmail.com

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status** 

PΙ

PD Cause:4038 Could Not Duplicate Concern Unknown

S fired on safe release Concern: 1007 Fired on Safe Release

 $\mathbf{C}$ 

4/12/10 Per note with rifle, "3 yrs ago pulled trigger did not fire. Touched bolt weapon fired. While cleaning rifle would fire when safety was released. Local gun dealer cleaned trigger assembly and adjusted in Nov 2009 pulled trigger rifle did not fire touched bolt rifle fired. Happened again in Dec 2009. Local dealer cleaned trigger assembly and adjusted trigger."cm

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM Remington CF/BA 700/280 REM 26961 D6212052 BP 1/6/1995

Where Purchased **Original Owner Date Purchased** Accessories

JERRYS SPORT CENTER INC FRONT HALF OF SCOPE BASE U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement Remington/700/CF/BA

Reim. Date Cash Cash Date Release Date Settlement Release of Claims Reimbursement Settlement APV APV

Per Ilion, replace TPA at n/c

> Repair/Replacement Repair/Replacement Cost Date 47.23 4/12/2010

4/12/10 Could not duplicate concern. Safety works hard. Replace TPA at n/c.cm

Examination[Remington/CF/BA]

**Part** Sub-Part Code Comment **B.TRAVIS** Examiner Exam Date 4/1/2010 Product Type RF Examination Action Type Assigned To F.SUPRY Could Not Duplicate TPA HAD BEEN CLEANED AND ADJUSTED AT PATHFINDER 4038 Cause Concern SPT GOODS AFTER INCIDENT 22" 280 REM Description Date Code BP Bore Plugged False Barrel Bulged False False Fired

Principispiay			rage 2 01 2
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
	Lug Condition	Slightly Worn; l'unctioning	HEADSPACE IS OKAY. BOLT WOULD NOT CLOSE ON EXT.MAX PLUG
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description	]	STANDARD M/700 SAFETY
Safety	Function	Slightly Worn; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.011
Sear	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test	10363	False	
Trigger	Condition	Slightly Worn; Functioning	SAFETY WORKS HARD
	Pull	Select	8#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		FRONT HALF OF SCOPE BASE

J dishistand led the trigger Assy from the Receiver and Removed SEAR. Trigger was agrunted up with oily whenith this was against all trigger was reduced and light of was again adjusted cleaned of REASSEMBLED. The trigger was too light of was again adjusted ALAN BORGE - PATHER WHER FORMING GOODS

How often do you lubricate the bore? (Months or Number of rounds)

How often do you lubricate the action? (Months or Number of rounds)

How often do you lubricate the trigger assembly? (Months or Number of rounds)

Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?

Comments:

When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?

What were the services performed?

5212052 ARMS CO., INC



el Post to:

Service Divison efler Ave IY 13357

N YOUR FIREARM OR IN THE SAME BOX WITH THE IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE IME, ADDRESS (WITH ZIP CODE), TELEPHONE AND

- :: Record the serial number of your firearm before sending it.
- :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)
- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.
- :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

- :: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)
- :: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair, estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card.

salety works hand hopoce TPA A+N/L

# 230145

4469

BP 1/95 8# 1011

## Remington.

Factory Repair Instructions

(NOTE: Please print an	d complete this form, a	and then include i	t with your firearm.)
------------------------	-------------------------	--------------------	-----------------------

Model Number: 700 *	Serial Number: DL212052					
Are you the original owner?: NO						
Name: JOHN R (OX	Date of Purchase: 2665					
Address (no PO Boxes):						
104 WALNUT HILL LANE						
city: GASSAWAY	State: WV zip: 26624					
Phone (Daytime): 304-364-2270	Fax:					
E-mail Address: JOX 3546 @ GMAIL, COM  would like to receive future e-mail updates from Remington.						
Please describe your problem: 3 YEARS AC	60 PULLED TRIGGER DID NOT					
FIRE. TOUCHED BOLT WEAPON FIRED WHILE CLEANING						
RIFLE WOULD FIRE WHEN SAFETY WAS RELEASED. LOCAL						
GUN DEALER CLEANED TRIGGER ASSEMBLY AND ADJUSTED						
IN NOV 2009 PULLED TRIGGER RIFLE DID NOT FIRE						
TOUCHED BOLT RIFLE FIRED	HAPPENED AGAIN IN					
DEC 2009. LUCAL DEALER	CLEANED TRIGGER ASSEMBLY					
AND ADJUSTED TRICCER						
Ammunition Information:						
Manufacturer: NORNADY Type:						
Other (i.e. bullet weight/type, shot size, powder):	No. 10 40 40 10 10 10 10 10 10 10 10 10 10 10 10 10					
139 CRAIN SST						
Handload Information:						
Powder Used:	Powder Weight:					
Case/Hull Used:	Primer Used:					
Bullet Type/Shot Size:	Reloader Used:					
Firearms Care (Cleaning and Lubrication):						
Brand of cleaning solution used: HOPPEIS NO. 9 SOLVENT						
How often do you clean the bore? (Months or Number of rounds) ANNUALLY						
How often do you clean the action? (Months or Number of rounds) RUNUALLY						
How often do you clean the trigger assembly? (Months or Number of rounds) ANNUALLY						
Brand of lubricant used: HOPPEIS NO. 9	LUIBRICATING OU					

Arms Services Repair & Estimate System	
File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports : Table Maintenance Syste	m Maintenance Help
🛪 Repair Inquiry	
Repair Number: RE 00192755 Serial: D6212052 Model 700 Center Fire Calber: Repairment Bruce Travis 280 REM Produced: 01/05/1995	<b>人名英格兰 医克尔斯氏原生物 化自己原始性</b>
Verify Repair Status: Repairing 4/1/2010 9:44:04 AM	
Address Information  Customer: Received From Return To: C. Received From	
Name: JOHN COX JOHN COX	医电影电话 医多克斯氏 电电影 化二氯甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基
Addiess 1:   1104 WALNUT HILL LN           1104 WALNUT HILL LN           Addiess 2         PO Box         PO Box	and the second of the second o
Crity (GASSAWAY GASSAWAY GASSAWAY Country (US State: WV Zip Code: 126624 Country (US State: WV Zip Code: 126624 Country (US	The control of the co
Contact / Condition Problems Estimate   History / Status   Shipping / Billing	A construction of the first the transfer of the first the second
Current Status	with the property and the property of the prop
Date   Code   User ID   Desc1   I Shipping Hold   Repairing   3/25/2010 11:49; New   thomaspe   Repair Added   I Intel® ace Hold   4/1/2010 9:44:04 AM	and the property of the state o
3/25/2010 12:05 Email/Verified AmmEmail Receipt Estimate Sent System	7. 18. 18. 19. 19. 19. 19. 19. 19. 19. 19. 19. 19
4/1/2010 3/41/24 Maint Travisbw Repair Maintenance Pets Received Repair Location 4/1/2010 9/42/42 Estimate Travisbw Estimate Update Passed Inspection ILN	
4/1/2010 9:44:04 Repairing System Immediate SAP Allocation  All CMIO 31:30-5 Function Received Current Location  Return As Received Current Location	
Has been Approved ILN Transfer Number	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
	多名数 <b>的复数存在的</b> 中的分别的变形的。
Repair Search Close	<b>,一个人的一个人的一个人的一个人的一个人的一个人的一个人的一个人的一个人的一个人的</b>
and the first for the highest state of the first state of the	wall problem that there is a proper and a problem from
在自己的联系的 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	and the state of t
· · · · · · · · · · · · · · · · · · ·	于1965年14年上午年14日中国共和国共和国共和国共和国共和国共和国共和国共和国共和国共和国共和国共和国共和国
网络马格里斯士主教士斯士特州 化多个工作用 医生物交换 化化	<b>学,中国一个企业工程的企业工程,</b>
	在1. 100 A 200 TO TO TO TO TO A 1. 100 A 200 A
10. 10. 10. 10. 10. 10. 10. 10. 10. 10.	<b>这个意思的是是一种的大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大</b>
<b>刘克元姓氏表示公司前来他们自己的主义表面这些人要求自己的</b> 第四	· · · · · · · · · · · · · · · · · · ·
· 100 · 100	
Land to the first the second s	
The second secon	化物质的 医多种性神经病 医多种性神经病
· · · · · · · · · · · · · · · · · · ·	
· 10 · 10 · 10 · 10 · 10 · 10 · 10 · 10	
at the street of the property said to be the street of the	
suppil 4/1/2010 1:54 PM COPS NUM 2 (NS 327)	
Bolant Color Mission Color Col	

12 15 26.23

DECEIVE L APR - 6 2010 BY: