Remington Arms Co., Inc.
Product Service
Legal Case #:4171

	T 0	
1 300	Inforn	กลร์เกท
Casc	TITIOTI	nanon

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 184275 184276 12/28/2009 12/29/2009 12/29/2009

Customer Information

Type **Business** First Name City Contact Last Name Street State Zip Age 55874 Dalia Rd. H 970-323-5745 Reporter Joe Percival Olathe CO 81425

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

S

PD Cause:4038 Could Not Duplicate Concern

Unknown

C Fired on Safe release

Customer reported - Have to take off Safety to open bolt & has fired doing this. dmf

Concern:1007 Fired on Safe Release

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM

Remington CF/BA 700/243 WIN \* 6398082 XT 12/1/1970

Date Purchased Where Purchased Accessories Original Owner

GATEWAY CO KAN C MO TWO PIECE SCOPE BASE U

CONCERN:FSR

Mfg.TypeModel/Ga.SKUSerialBbl.DOMRemingtonCF/BA700/270 WIN\* A6295861 KI 5/5/1976

Date Where Purchased Accessories Original

Purchased Where Purchased Accessories Owner

WESTERN HOEGEE GLENDALE TWO PIECE SCOPE

U

CA BASE CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement Release Date Reimbursement Release Date Re

Repair under BLSM program at special price

Repair/Replacement Repair/Replacement

Cost Date \$93.68 12/30/2009

12/30/09: Per Fred S.- Could not duplicate concern. Trigger assembly very dirty. Replace trigger, check over, clean under

BLSM program. dmf

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/29/2009
Examination	Product Type		RF
	Action Type	7	A
	Assigned To	Ī	F.SUPRY
Cause	4038	Could Not Duplicate Concern	
	Description		22" 243 WIN
	Date Code		XT
	Bore Plugged	False	
Barrel	Bulged	False	
Darrer	Fired	False	
	Fired while Obstructe	d	<del></del>
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Worn; Functioning	
Overall	Stock Condition_	Worn; Functioning	
····	Fore End Condition	Select	
Receiver	Condition	Worn; Functioning	
	Bulged	False	<u></u>
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
· · · · · · · · ·	Function	Like new; Functioning	
	Lift	Select	.009
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
eeding Test	Tests	False	
<del></del>	Condition	Slightly Worn; Functioning	VERY DIRTY

	Pull	Select	4.5#
Trigger	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/29/2009
Examination	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
	Description		22" 270 WIN
	Date Code		KI
	Bore Plugged	False	
Barrel	Bulged	False	
Barrer	Fired	False	
	Fired while Obstructe	d	
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	HAS BEEN REFINISHED
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	

Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Lift	Select	.009
Sear	Notch	Slightly Worn; Functioning	
	T4-	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	DIRTY
Trigger	Pull	Select	5.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

Arms Services Repair & Estimate System		E F X
	Tools CSR Tools Reports Table Maintenance System Maintenance Help	
₹ Repair Inquiry		379
Repair Number: RE00184275 Serial: 6398082 Model 700 Center Fire	with 22 Repairment Bruce Travis	中間禁制
Verify Repair   Verify Repair	Status: Approval-Hold 12/29/2003 4:42-40 AM	
Address Information	return To: C Received From	<b>经产品</b>
■ Fig. 1 constant Control C	0E PERCIVAL	
Address 2 PO Box	5874 DALIA RD. PO Bod	
City: OLATHE O State: CO Zip Code: \$1425 Country: US State: C	DLATHE D Zip Code: 191425 Country US	<b>"一条保护</b> "
FL.		116 B 11 1
Contact / Condition Problems Estimate	History / Status Shipping / Billing	Sales Services
Date Code User ID Desc1	Current Status  G: Shipping Hold Approval Hold	(海擊衛)
12/28/2009 12:2! New baileyrl Repair Added   12/28/2009 12:2! Expedite baileyrl From: Check In	Interface Hold   12/29/2009 4:42:40 AM	Part No.
12/29/2009 4:39: Maint   Travisbw   Repair Maintenance   12/29/2009 4:42: Estimate   Travisbw   Estimate Update	Estimate Sent Approve ack Peats Received Repair Location	
12/29/2009 4:43: Expedite Travisbw From: Repair Bench   12/29/2009 6:00: ApprovalHold System Immediate SAP Allocati	Passed Inspection ILN	-distance of
	Return As Received Current Location Has been Approved LLN	<b>提供</b> 基本
The same of the sa	I Internal Repair Transfer Number	
Repair <u>S</u> earch	Refresh Close	<b>我就我们</b> 是
	Tenes, 1 Zon-1	
A STATE OF THE STA	Control of the Control of the Control of Earth and Control of the	
。		A House
Again the graph of the Market and the second		
	等10.000 (1.000 1.000 1.000 1.000 1.000 1.000 1.000 1.000 1.000 1.000 1.000 1.000 1.000 1.000 1.000 1.000 1.000	
Commence of the commence of th		
	en transferior de la company de la compa	a de la compansión de l
	and the control of th	
CONTRACTOR OF THE PROPERTY OF THE PARTY OF T		
The Art of the Section of the Sectio		
[14] [14] [14] [14] [14] [14] [14] [14]		e la Marina de Production
[2/29/2009 [8:02 AM [C275]	NUM FIRS SCRIL	
supyl 12/29/2009 8:02 AM CCPS  Start Decides (Research of the services Research of the services		a la la la la cina de la

	EC	رَدُ	a <u></u>		
Щ	DEC	3	0	. ₩ <u>[</u> 2009	رنال
В					

4171



22" 4.5#

## General Repair Form

Back to Repair Services

NOTE: Please complete and print this form, and then include it with your firearm

Model Number: ## 700	Serial Number: 4 4 3	98082		
Name: Joe Percival	Date of Purchase:			
Address (no PO Boxes): 55874 Dalia Rd.				
City: Olathe	State: CO	zip: 81425 1		
Phone (Daytime): 970-323-5745	Fax:			
E-mail Address:				
Please describe your problem:				
Bolt action - have to take off				
Safety to open bo				
fired doing this	_			
,		243 Win.		
500 characters left				
Consist Center for services provided and estimated repair time.				

6398082 Model: 700

)UR FIREARM OR IN THE SAME BOX WITH THE :EEL YOU MUST SEND SPENT SHELLS PLEASE SEND RESS (WITH ZIP CODE), TELEPHONE AND MODEL AND

hipping and handling. Preferably, ship in a

mage. sington is not responsible for damage or loss syour carrier.

Investor Relations | Other Remington Brand Products | Legal ...

Renington.

Visit Our Other Websites

could not duplicate concern.
This, Assm. very Dirty.
Hybree TPA chekovery chan
under bolt Lock program Rom.
Bro.00 + SKH.

Quote

DEBBIE PERCIVAL (970) 323-5745 55874 DALIA RD OLATHE CO 81425 17 LBS 1 OF 1 SHP.WT: 17 LBS DWT: 27.8 LB5 DATE: 16 DEC 2009

SHIP ATTN BL SAFETY PROGRAM TO: REMINGTON ARMS CO INC. 14 HOEFLER AVE



LION NY 13357-1888



NY 135 0-01

UPS GROUND

TRACKING #: 1Z 810 300 03 4793 2521



BILLING: P/P

ISH 11.00 E2844 96.5A 10/2009

International Strapting Nation - Century Internationals that or explored to the ruse statisting as readity more other tentus professional Centuria Medical Residence of the Century Strategy of the Contraction of the Contrac

∾Arms Services Repair & Esti				<u>₽</u> ₽×
File Add Repair Estimate Repair Expedit	te Repair   Iniquiry   Répair Tools   CSR To	ools Reports Table Mainténance S	stem Maintenance (Help)	1.00 55 1248 1588 458 5 T.
Repair Number: BE00184276   Seriel	A6295861 Model 700 Center Fire with 22 Rep	airmant Bruce Travis		
Verify Repair 05/05/	arrel Caliber 270 WIN Produced: /1976	Status: Approval-Hold 12/29/2009 4:4523 A	M and the second	
Address Information Customer	11000110	Received From		
Name: JOE PERCIVAL Address 1: 55874 DALIA RD.	JOE PERCIVAL 55874 DALIA RD.		and the state of the state of	
Address 2 PI City OLATHE State CD Zip Code: 81425	O Box:	PO Boxd	$m_{i} > 1, 1, \dots$	
2p Lode, P-22		81425 Country US		
Contact / Condition Problems		story / Status Shipping / Billing		(1) (1) <b>基本企业</b>
Date   Code   User ID   12/28/2009 12:3! New   badeyil	Dennis Addad	Current Status Shipping Hold ApprovalHold		
12/28/2009 12:4/ Expedite valentds 12/29/2009 4:38: Maint Travisbw	From: Check In	InterFace Hold 12/29/2009 4:45:23 Al Estimate Sent ApproveRack		
12/29/2009 4:45: Expedite Travisbw	From: Repair Bench	Parts Received Repair Location Passed Inspection ILN		
12/29/2009 6:00: ApprovalHold System	Immediate SAP Allocation	Return As Received Current Location Has been Approved		
		Internal Repair Transfer Number		
Repair <u>S</u> earch		Refresh Close		The second second
	And the second s	e de la companya de l		
				and the property of the property of the second
and the second second				不是其一人的人
	en de la Companya de La Companya de la Co	Andreas San Comment of the San C		
	range samma pagana Abe Oracido de Capada A april 1985	r en komplete komboniste en som Little komboniste komboniste komboniste komboniste komboniste komboniste komboniste komboniste komboniste komb		The same of the sa
			and the second s	
	operation of the second second second	North Maria Control (1987)		The state of the state of the state of
	Maria de la consta	to the state of the con-	A Committee	
		Andrew Line and the	and the state of t	on from Court, as a substitution of the Court of the Cour
	or the last of the			Statement of the second
suppl (12/29/2009)	8:04 AM ACCOR SALE SALE NUM	Marcon Silvin Social Social Service		ZZO (OSZOCZEJO ODAZA)
a start Dipper Selection	The state of the s			A CHANGING TAXA A SAME AND A SAME

	ZC	رَوَ	7		
	DEC	3	0	. ₩ ፲ 2009	
B,	Y:			*	

4171



22" 16. I 5/76 5.5"

## General Repair Form

RE00184276

REMINISTER

Back to Repair Services

NOTE: Please complete and print this form, and then include it with your firearm

Model Number: # 700	Serial Number: # A6295861			
Name: Joe Percival	Date of Purchase:			
Address (no PO Boxes): 55874 Dali	a Rd			
City: Olathe	State: C_O Zip: 81435			
Phone (Daytime): 970 - 323 - 5745	Fax:			
E-mail Address:	also.			
Please describe your problem:	and the second s			
off safety to open bolt and has fired & doing this. 270 win.				
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.  (1) WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE  WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE  OR SPENT SHELLS PLEASE SEND  OR SPENT SHELLS PLEASE SEND				
00	shipping and handling. Preferably, ship in a amage. mington is not responsible for damage or loss n your carrier.			

Visit Our Other Websites
Other Sites

Could not duplicate concern Tilig. ASSM Disty. Replace TPA, check over, clean under Bolt Lock program for \$ 70.00

Queste