Page 1 of 2 **PrintDisplay**

> Remington Arms Co., Inc. Product Service Legal Case #:6214

Case Information

Incident Date RE# **Date Opened** Date Opened(PS) **Date Closed** Pre Lit Lit Obsolete 232377 5/27/2011 5/18/2011 5/31/2011

Customer Information

Type **Business** First Name Last Name Street City State Zip Contact Age Incident Howard McCracken, Jr 1768 Turquoise Ct Virginia Beach VA 23456 H 757-471-2576

Incident Information

Claims Repair Est. Codes Medical Treatment **Medical Status**

PΙ

PD Cause:4038 Could Not Duplicate Concern

Unknown

S Fires when closing bolt Concern: 1008 Fired on Bolt Closing

5/18/11 Per call from McCracken, he bought this rifle new in 1987 and has only shot it once. He had an accident (unrelated to Remington) and has been on disability since. He has cleaned it in the years in between and found that it would fire when he closes the bolt. He has never made any adjustments to it.cm

Firearm Information

Mfg. Remington

Type CF/BA Model/Ga. 700/30-06

SKU 25773

Bbl. DOM Serial

Date Purchased

Where Purchased

Accessories

Original Owner

B6659791

GREEN TOP SPTG GOODS 23060

Y

Purchased new around 1987.

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement Date APV

Reim.

Cash Date APV

Per Ilion, replace trigger plate assm, clean and test fire at 1/2 normal cost

> Repair/Replacement Cost

Repair/Replacement

Date

47.40 6/10/2011

5/18/11 Sending ARS. Ordered box to be sent from factory.cm 5/31/11 Per Ilion, "could not duplicate concern.trigger assm dirty, sticky parts work sluggish. replace trigger plate assm, clean and test fire at 1/2 normal cost." Called McCracken and he approved the charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		5/31/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		XE
	Bore Plugged	False	
	Bulged	False	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6214&Type=Case

6/10/2011

Į	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	7
	Firing Pin	Slightly Worn; Functioning	
Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	WORKS SLUGGISH
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	.014
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test	10515	False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,STICKY PARTS WORK SLUGGISH
	Pull	Select	9#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	

22" XELY84 9#

6Z19 May 18, 2011

Howard McCracken, Jr 1768 Turquoise Ct Virginia Beach, VA 23456

Subject: #6214


Dear Mr. McCracken,

Thank you for your patience. Enclosed is the UPS ground prepaid shipping label to cover shipment of the firearm for inspection at our factory. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure firearm is logged in correctly.

I apologize for the inconvenience and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com



enclosure



could not dup licate concern.

T.A. dirty + Sticky, parts work
sluggish. Replace TPA, clear+
Test Pine At 1/2 Normal Lost.

Quote

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

	
Model Number: 700 ADC 30-06	Serial Number: 8665 9791
Are you the original owner?: YES NO	
Name: Howard J. McCracker JR	Date of Purchase: . 1/-16-87
Address (no PO Boxes): 1768 Turquo	
City: VIRGINIA Beach	State: VA. Zip: 23456
Phone (Daytime): 757-471-2576	Fax: NON E
E-mail Address:(if e-mail address is provided, notification	of receipt and shipment will be
sent) NONE	
E-mail Address:	
I would like to receive future e-mail updates from Ren	nington.
Please describe your problem and date of occurrence:	
win I pull the	bolt back
and Fordwor	d It will
Fire by itself	
The second secon	
I use Ballis	T./
20 + 46613	10上
500 characters left	
Ammunition Information:	
0	26 -1 10
Manufacturer: Remington	O Guain SOFT Point
Other (i.e. bullet weight/type, shot size, powder): 18	O Guara SOFT POINT
·	X X X X X X X X X X X X X X X X X X X
Handload Information:	
Powder Used:	Powder Weight:
Case/Huil Used:	Primer Used:
Bullet Type/Shot Size:	Reloader Used:
Denet Typeroffict Olde.	Trefocuer Gazo.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	5/18/2011	REQUESTED BY:	ВН
QUANTITY:	1	WEIGHT PER PACKAGE:	10
PLEASE CHECK ONE			
MEDIA			
COORDINATOR			
TO MAIL		I WILL MAIL	
DESCRIPTION:			
Model 700			
B6659791			

LABEL INFORMATION

MAIL LABEL TO: 757-471-2576 Howard McCracken 1768 Turquoise Court Virginia Beach, VA 23456	
RETURN ITEM TO: Ilion- REM	

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

4XX596 SVC GNDCOM TRACKING# 124 REF 1:HOWARD REF 2:700/B66	MCCRACK	ACT L 664274	10.0 00	CURR LBS	USD	1 OF
HANDLING CHAR SINGLE-PIECE DV 0.00 DC 0.00 AH 0.00 TOT PUB CHG	PUB RAT	COD DGD PR	SS: 0.00 0.00 0.00 PUB+HA		RS SD SP	T/P USD 0.50 0.00 0.00 8.96





