				Remington Arms (						
				Product Servi						
				Legal Case #:6	878					
Case Inform <b>RE#</b> 251116	nation Date O 12/19/	•	Date Opened(P 11/21/2011	S) Date Cl 12/20/2		ncident Date	e Pre	Lit I	Lit .	Obsolete
Customer In	nformation									
Туре	Business	First Name	Last Name	Street	City	State	Zip /	4 ge	Co	ntact
Incident		Leroy	Bateman	259 Quail Ln.	Merritt Isl	and FL	32953	I	H 321-	454-7363
Incident Inf	formation									
Claims		(	Codes	Re	pair Est.	Medical T	reatment	ĩ	Medica	I Status
PI										
PD			nproper Maintena			Unkr	nwn			
S	(	Concern:1007 Fi	red on Safe Rele	ase		0 Inc				
C FSR										
11/21/11: C	Sustomer call	ed in. He said th	his rifle had FSR	years ago. He said h	he saw someth	ing on 60 Mi	nutes. df	****		
Firearm Inf	ormation									
Mf	ģ.	T	ype	Model/G	a.	SKU	Se	rial	Bbl.	DOM
Remir	ngton	CF	/BA	700/7MM RE	M MA	n/a	A66	47664	WP	8/28/1978
Date Pu	rchased		Purchased	Accessor		riginal Own	er			
		KEI K MART	F SPARKS NV	SCOPE BA	ASE	Y				
CONCERN	1: FSR									
Ammunitio	n Informatio	n - None Define	ч							
		tion - None Defi								
Settlement										
				Remington/700/0	CF/BA					
Sett	lement	Release	of Claims	<b>Release</b> Date	Reimb	ırsement	Cash Settlement		. Date PV	Cash Date APV
	Quote to repa er BLM	uir								
			placement ost	Repair/Replaceme Date	nt					
		\$29	9.44	1/8/2012						
			22/11: Per Ilion - er mailed in quote	TA has a dried lub w/payment. df	c residue caus	ing parts to bi	nd. Replace	: TA, cle	an & te	est fire

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date	]	12/20/2011
Examination	Product Type	]	RF
	Action Type		A
	Assigned To	]	T.NAGLE
Cause	4015	Improper Maintenance	
	Description	] .	24" 7MM REM MAG
	Date Code		WP
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	]
	Fired while Obstructed	]	

 $http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=\!6878\&Type=\!Case$ 

1/8/2012

	Muzzle/Crown	Slightly Worn;	
	Condition	Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
·	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.011
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn: Not Functioning	HAS A DRIED LUBE RESIDUE PARTS BINDING WILL FOLLOW DOWN
Trigger	Pull	Select	10+#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE

 $http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=\!6878\&Type=Case$ 

1/8/2012

#### QUOTATION

## Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700 Madison, NC 27025-0700

Parts/Repairs Fax

irs 800-243-9700 Marison, NC 27025-0700 336-548-7801 *www.remington.com info@remington.com* 

## ALL PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (4) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 15 DAYS, WE SHALL RETURN THE ITEM(S) AS RECEIVED POSTAGE DUE.

Repair Order N RE00251116 Account # - R-	umber	Description/Serial I A6647664	Number	Date Received - Estimate Date - Current Date -	12/19/2011 12/20/2011 12/20/2011
			<del>Fax</del> E <u>mail</u>	Return To MERRITT ISLAND GUN 3420 N COURTENAY PA UNIT #2 MERRITT ISLAND. FL 32 1-59-009-01-2L 112012	RKWAY 2953 US
PO Number Daytime Phone ( Approval: Custo	AEX DISCOVER Car <sup>,</sup> 321) <u>454-7363</u> omer Signature <u>J</u> esire Any Change Please Use	· (1) •		S Ang Mark This DOX	3 - <u>12-30-11</u>
Reported			blems <u>Found</u>		··· · · · · · · · · · · · · · · · · ·
M123	FORWARD TO PRODU FOR INSPECTIO	JCT SERVICE	M123	FORWARD TO PRODU	CT SERVICE F
ProblemNotes	test fire under bolt lock	l lubrication residue program for \$20.00	+ shipping	ts to bind.replace trigger plate a	ssm,clean and
Material #	Estimate **C.O.D. // Material Description	Shipping and Handli	ng Charges are <u>Qty</u>	NOT Included in this Quote Warranty Price/ Discount	t <u>Extended</u>

<u>Material #</u>	Material Description	<u>Qty</u>	<u>Warranty</u> <u>Y/N</u>	<u>Price/</u> Unit	<u>Discount</u> Percent	<u>Extended</u> <u>Amt</u>
Part						
F305570B	X-MARK PRO 700 TRIG ASSB RH BLACK (O	1	Y	\$94.00	0%	\$0.00
Service						
4000114	GR-SHIPPING & HANDLING (GUN REPAIR)	1	N	\$17.00	0%	\$17.00
4000116	GR-LABOR	1	N	\$20.00	0%	\$20.00
4000119	GR-TEST	1	Y	\$23.00	0%	\$0.00
				Sub Total	l:	\$37.00
				Est. Sales '	Гах:	\$2.22
				Grand To	otal:	\$39.22
			Mกดดศ	CM		
			UPPNUV	LU		

98/7 1014 101

6878

November 21, 2011

Leroy Bateman 259 Quail Ln. Merritt Island, FL 32953 Phone: 321-454-7363

#### Ref: #6878, Model 700, Serial # A6647664

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination and service request.

Please include a copy of this <u>letter and service request</u> to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope this action will keep you a loyal Remington customer.

Sincerely, Dell Fulcher Consumer Affairs Administrator Remington Arms Co., LLC Phone: 1-800-243-9700 press 0 and ask for ext 2680 EIT WE Fax: 336-548-7872

enclosure



J.A. has a doried lube residue causing parts to BIND. Mplace TPA, clean pestRine under FLP Con & 20. FShip

Quote

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

## Service Request

Parts and Repairs: P:800-243-9700/F:336-548-7801

### Remington Service PO Box 700



Madison, NC 27025-0700

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

Service Request Number	Serial Number / Description		Date of Request:	11/21/2011
SR00004365	A6647664		Date Printed:	11/21/2011
Customer: LEROY BATEMAN	Model 700 Center Fire	Destination: Arms Services		
259 QUAIL LN. MERRITT ISLAND, F	L 32953 US	14 Hoefler Ave Ilion, NY 13357	US	
Email:		Email:		
Your request for service on the returned. If not, you will be co	: item(s) will be evaluated by our repairman intacted with an estimate before work is per-	to determine if it is covered under our warranty po- formed.	licy. If it is your firearn	will be repaired and
				er na si Marana a sa sa sa sa sa sa sa sa
Reason For Return M123 - FORWARD TO I	PRODUCT SERVICE FOR INSPECTI	ON		
Service Request Section Product Service# 6878 - FS		le se la lestre estatel d'un		
Parts And Service Details Material Type	Description	Qty Warranty Needed	Price	Disc Amount
	:			
THIS IS NOT AN INVOICE. I	his is a pre-estimate to repair, recondition, c	or replace the item(s)	Sub Total:	.00
being sent based on the convers			Est Sales Tax:	

Serial Number: Model Number: A 6647664 7MM 700 MAG Model Date of Purchase: Name: 1 - NOV - 1980 Address (no PO Boxes): 25 QUAIL LANE Zip: 32953 City: MeR State: /~ / ISLAND Phone Fax: 454-7363 (Daytime): ЭД E-mail Address: Please describe your problem: RIFLE FIRED WHEN I Took FIRED SINCE 1981. 500 characters left NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.  $\square$ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier. Print Reset

http://www.remington.com/asp/general\_repair\_form.asp

11/15/2011

# ARS LABEL REQUEST FORM

DATE:	11/21/2011	<u></u>	Service Request #	SR00004365
QUANTITY:	<u>l</u>		WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	fulcherdm	<u></u>	email address:	I WILL MAIL LABEL
Business:		· · · · · · · · · · · · · · · · · · ·		
Dusiness.		Remington Servi PO Box 700 Madison, NC 27 www.Remingto	7025-0700	
			FORMATION	· · · · · · · · · · · · · · · · · · ·
MAIL LABE	L TO:	LEROY BATEN 259 QUAIL LN. MERRITT ISLA SR00004365		
		Email:		
<b>RETURN I</b>	ГЕМ ТО:	ILN		
		Arms Services		
			· · · · · · · · · · · · · · · · · · ·	
		4XX596 SVC GND TRACKIN REF 1:S REF 2	NOV 21, 2011 ALL C COM ACT UT 10.0 LE G# 1Z4XX5969066776417 R00004365	JRR USD 1 OF 1 3S
K		SINGLE- DV 0.00 DC 0.00 0H 0.00	DGD 0.00	SVC T/P USD RS 0.50 SD 0.00 SP 0.00 LING 10.27
ATTN	duct Service			
$\mathcal{I}$				· · · · · · · · · · · · · · · · · · ·





