				duct Ser					•	
nation	<u></u>								·	
Date	Opened	Date Oper	ned(PS)	Date (losed	Inc	ident D	Date	Pre Lit	Lit Obsolete
8/7	//2012	. 8/20/2	012	8/20/	2012			-		
nformatior	ı									
Business	First Name	Last Name	Street		City	State	Zip	Age	C	lontact
	David	Bonner	807 Hill Side	St SW	Valdese	NC	28690		E david.bon	ner@ncsbins.com
formation										
Claims			Codes			Repair	Est.	Medic	al Treatment	Medical Status
		Cause:401	5 Improper N	laintena	nce			т	Inles or m	
S Fired when releasing safety		Concern: 1007 Fired on Safe Release		UNKNOWN						
5	Date 8/7 nformation Business formation Claims	Date Opened 8/7/2012 Information Business First Name David ormation Claims	Date Opened Date Opened 8/7/2012 8/20/2 aformation Business Business First Name David Bonner ormation Claims	nation Date Opened Date Opened(PS) 8/7/2012 8/20/2012 nformation Business First Name Last Name Street David Bonner 807 Hill Side formation Claims Codes Cause:4015 Improper M	nation Date Opened Date Opened(PS) Date C 8/7/2012 8/20/2012 8/20/2012 nformation Business First Name Last Name Street David Bonner 807 Hill Side St SW formation Claims Codes Cause:4015 Improper Maintenau	Date Opened Date Opened(PS) Date Closed 8/7/2012 8/20/2012 8/20/2012 aformation Business First Name Last Name Bouner 807 Hill Side St SW Valdese ormation Codes Claims Codes	nation Date Opened Date Opened(PS) Date Closed Inc 8/7/2012 8/20/2012 8/20/2012 nformation Business First Name Last Name Street City State David Bonner 807 Hill Side St SW Valdese NC formation Claims Codes Repair Cause:4015 Improper Maintenance	nation Date Opened Date Opened(PS) Date Closed Incident E 8/7/2012 8/20/2012 8/20/2012 nformation Business First Name Last Name Street City State Zip David Bonner 807 Hill Side St SW Valdese NC 28690 formation Claims Codes Repair Est. Cause:4015 Improper Maintenance	nation Date Opened Date Opened(PS) Date Closed Incident Date 8/7/2012 8/20/2012 aformation Business First Name Last Name Street City State Zip Age David Bonner 807 Hill Side St SW Valdese NC 28690 formation Claims Codes Repair Est. Media Cause:4015 Improper Maintenance	aation Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit 8/7/2012 8/20/2012 aformation Business First Name Last Name Street City State Zip Age C David Bonner 807 Hill Side St SW Valdese NC 28690 E david.bon formation Claims Codes Repair Est. Medical Treatment Cause:4015 Improper Maintenance

si/iz Per letter wher a eneves unis nile le in the 1960's. chambered a round and it did not feel like it went in smoothly. To make sure nothing was wrong he pushed the safety off to open the bolt and upon doing so the gun fired.cm

Firearm Information						
Mfg.	Туре	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	230135	WN	8/1/1966
Date Purchased	Where Purchased	Accessories	Original Owner			
		2 PC. BASE & RINGS	N			
CONCERNI, ESB						

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

]	Remington/700/CF/BA				
Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date
Per Ilion, replace TPA, clean and test fire at BLSM price						
	Repair/Replacement	Repair/Replacement				
	Cost	Date				
	99.94	8/31/2012				
8/31/12 Per Ilion, could not duplica	ate concern. Trigger assm	very dirty and sticky cau	ising parts to work	sluggish. Rep	lace TPA, cle	an and test

fire at BLSM price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B. TRAVIS
	Exam Date		8/20/2012
	Product Type		RF
	Action Type		A
	Assigned To		T. NAGLE
Cause	4015	Improper Maintenance	
Barrol	Description		22" 3006 SPRG
	Date Code		WN
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7852&Type=Case

8/31/2012

,

	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overail	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
· · · · · · · · · · · · · · · · · · ·	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.009"
Sear	Notch	Slightly Worn; Functioning	
	T	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	VERY DIRTY AND STICKY
r-:	Pull	Select	4.5 LBS
Trigger	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		2 PC. BASE AND RINGS

.

.

Print	7852 Page 1	012
Subject:	Model 700 misfire [Incident: 111214–000143]	wp8/4 4.5
From:	Remington Information (info@remington.com)	0,09
To:	djbonner2@yahoo.com;	

Date: Thursday, December 15, 2011 8:49 AM

Recently you requested personal assistance from our on-line support center. Below is our response.

If this issue is not resolved to your satisfaction, you may reopen it within the next 7 days.

Thank you for allowing us to be of service to you.

To access your question from our support site, click here.

Subject S#230135 Remington Model 700 Model 700 misfire

59

Discussion Thread

Response Via Email (Frank)

We regret you are experiencing a problem with your Remington product. We would like to speak to you in more detail regarding your inquiry. If you will please contact our Parts & Repair Department with your SERIAL NUMBER, at 1-800-243-9700 Mon-Fri 9-5 EST, our representatives can assist you with this matter.

Customer By Email (david bonner)

Hello, my name is David Bonner from North Carolina. I have an older Model 700 30-06 bolt action. It has a metal butt plate and although I am not the original owner, I believe it was probably made in the 1960's. While I was hunting several weeks ago I chambered a round and it did not feel like it went in smoothly. To make sure nothing was wrong I pushed the safety off to open the bolt and upon doing so the gun fired. Is there a fix to the problem with the http://us.mg4.mail.yahoo.com/neo/launch 12/15/2011

12/14/2011 08:26 PM

NECEIVEN AUG 2 2 2012

BY:----

12/15/2011 08:49 AM

older safety system or is there something else I can do? I have had the gun for about 10 years and have never had any problems with it and love to carry it. Any info. you can provide would be appreciated!

Question Reference #111214-000143

Product Level 1: Other Date Created: 12/14/2011 08:26 PM Last Updated: 12/15/2011 08:49 AM Status: Solved

inch

http://www.remington.com/safety -------- [---001:001844:42094---]

remove that rejety / \$ 37 20 Remington

14 Hoesler ave

Ilion NY 13357

atta SMP program



COULD NOT duplicate concern. T. A., VERY dirity & Sticky CAUSING PARTS to WORK sluggish. Rephace TPA, clear & rest fire under BLP for \$120. + ship Quot 12/15/2011

(taron) Olfedo (Stech) UPS





