Remington Arms Co., Inc. Product Service Legal Case #:8095

				Legal Case #:8095)					
Case Inform RE# 287111	mation Date O ₁ 10/26/2		Date Opened(P 10/29/2012	S) Date Close 10/29/2012		eident Da	te	Pre Lit	Lit	Obsolete
Customer I	nformation		•							
Type	Business	First Name	Last Name	Street	City	State	Zip	Age	C	ontact
Incident	•	Paul	Phillips	2033 Custer St	Allentown	PA	18104)-433-2029 ep@ptd.лet
Incident Int	formation	•				•				•
	Claims			Codes		Repair Est.	•	Medical Treatmer		Medical Status
PI -						-				
PD				Altered Adjustments or						
	res while reme	oving from	•	Components				Unknow	n	
safe C			Concern: 1007 F	Fired on Safe Release						
	note on SR,	gun fires while	removing from s	afe.cm						
Firearm Inf	formation									
Mfg.				Model/Ga.			sku	S	erial :	Bbl. DOM
•	Remington CF/BA			700/3006 SPRG			n/a			WI 8/20/1976
Date Purchased Where Purchas			ased	Accessories				al r		
		ON MFG ALI	LENTOWN	FRONT BOTTOM HAI	LF SEE THR	U	Owne U			
CONCERN	N:FSR	ra.		BASE						
Aitio	m Information	- None Define								
		on - None Define								
Settlement	ucts imormati	on - None Den	ined							
semement				Remington/700/CF/E	34					
	C (4)			-			. с	ash R	leim. D	ate Cash Date
	Settlement	ŀ	delease of Claims	Release Date	Keimb	ursement	Settl	ement	APV	APV
	eplace TPA, o SM program j									
at DL	Swi biogram I		pair/Replaceme	nt Repair/Replacem	ent					
			Cost	Date						
			29.44	11/9/2012						
11/9/12 Per	Ilion, trigger	assm set screv	s altered. Replac	e TPA, clean, test at BL	SM program	price.cm				
Examinatio	n[Remington	CF/BA]								
	Part		Sub-Part	Code		ــــــال		Comm	ent	
		Examine				B.TRA				
		Exam Da				10/29/2	012			
Examination	on	Product				RF				
Ī		Action T				T.NAG	TE			
Cause		Assigned		Altonod Adjustments on	- C		LE			
Cause		Descript		Altered Adjustments or	Component	si 22" 300	6 SDD			 1
		Date Cod				W1	N 3F K			
Barrel		Bore Plu		False		1 1				
Dan el		Bulged		False		4				
		Dulked		1 alse		4				
ı		FI .		i		1				

	Fired	False	
	Fired while Obstructed		_
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	7
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	7
	Block Condition	Select	1
Locking	Lug Condition	Slightly Worn; Functioning	<u> </u>
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	7
Overall	Stock Condition	Slightly Worn; Functioning	7
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	7
	Lift	Select	.010
Sear	Notch	Slightly Worn; Functioning	
	7	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING PROPERLY
m ta a a	Pull	Select	2#
Trigger	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		FRONT BOTTOM HALF SEE THRU BASE

/ Service Request

Reming on Service PO Box 700

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

건코 PIL

28/

Service Request Number | Serial Number | Description Date of Request: SR00031868 A6340556 Printed: Customer: PAUL PHILLIPS Destination: Arms Services 2033 CUSTER ST 14 Hoefler Ave ALLENTOWN, PA 18104 US Ilion, NY 13357 US

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

10/15/2012

10/15/2012

Reason For Return

M240 - BOLT LOCK SAFETY MODIFICATION

Service Request Section

GUN FIRES WHILE REMOVEING FROM SAFE

BA6340556 Model:



Parts And Service Details

Material

T.A. set screws a Henrid. Needed hp. TPA cleans trest under BUP Ron 820. + 9

Called on 10/15/12 gave serial Number was informed the rifle was mode in 1976. I purchased it bround 1979 have no real proof of purchase. I amthe only one to use it. Service requested is littled above.

Could not remove front scop to uplace mounts differently

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

e-mail pijmepeptd. net Est Sales Tax:

.00 .00

\$.00







