

Remington Arms Co., Inc.
Product Service
Legal Case #:7591

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
265014	4/17/2012	4/18/2012	4/18/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Dean	Ulrich	22172 Windward Way	Lake Forest	CA	92630		H 949-632-6727 E theugang@aol.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S FSR	Concern:1007	Fired on Safe Release	Unknown	
C				

SR# 15472 - Reason for Return: Perform safety checks on trigger assembly. Service Request Section: Accidental discharge when engaging safety. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	210451	CN	4/1/1966
Date Purchased	Where Purchased	Accessories	Original Owner			
		SCOPE,RINGS,BASE	U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$29					

4/19/12: Per Ilion - Could not duplicate concern. TA dirty, light rust. Can offer to replace TA, clean & test under BLM - quote. df 5/2/12: Customer apprvd & paid quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/18/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		CN
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,LITE RUSTING
	Pull	---Select---	4.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE,RINGS,BASE

Service Request

PO Box 399
Madison, NY 12025-0700

REMINGTON-UMC CORPORATION

228
CN4/66
4.5H

Parts and Repairs: P-800-9700/F-336-543-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guide for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number: SR00015472
Serial Number / Description: 210451

Date of Request: 03/19/2012
Date Printed: 03/19/2012

Customer:
DEAN ULRICH
22172 WINDWARD WAY
LAKE FOREST, CA 94035 US

Destination:
Arms Services
14 Hoefler Ave
Ilion, NY 13357 US

Email: theugang@aol.com

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return:
M310 - PERFORM SAFETY CHECKS ON TRIGGER ASSEMBLY

Service Request Section:
ACCIDENTAL DISCHARGE WHEN ENGAGING SAFETY.

Material	Type	Description	Qty Needed	Warranty	Price	Disc	Amount
----------	------	-------------	------------	----------	-------	------	--------

210451
Model: 700



RE00265014

RECEIVED
APR 19 2012

BY:

could not dup. connector
T.A. dirty, like rust can
open to replace TPR, clear
rust under RCP Ron
& W. T

Quote

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

Sub Total:	.00
Est Sales Tax:	.00
Grand Total:	\$.00





