.

÷

		Remington Arms Co., Product Service Legal Case #:9105			
Case Information		•			
RE# Date O	pened Date Open	ed(PS) Date Closed	I Incident Date	Pre Lit	Lit Obsolete
317317 8/8/2					
Customer Information	on				
	First Last	<b>-</b>			
Type Business	Name Name	Street	City State	Zip Age	Contact
Incident	Jacob Brothers	1345 Bowers Bridge Rd.	Manchester PA 1	<b>7345</b>	H 717-818-1415 ex
Incident Information	1				
Claims	Codes	<b>Repair</b> ]	Est. Medical Tre	atment	Medical Status
PI	00000	~~~ ••••••••			
	se:4015 Improper Ma	aintenance			
	cern:1008 Fired on Bol		Unknow	wn	
C C	cent. 1008 Filed on Boi	t Closing			
Per SK0005/448 Se	rvice Request Section,	"customer stated the rifle	e has fired several th	ne as the bo	It is closed." Jbi
Firearm Information	,				
		Model/Ga.	SKU	Serial	Bbl. DOM
Mfg. Remington	<b>Туре</b> CF/BA	660/243 WIN	N/A	105809	KR 5/1/1968
Date Purchased	Where Purchase		Original Owner	10,009	KK 5/1/1908
Date I ultilascu	where i urchases	a Accessories	U		
CONCERN: FBC					
Ammunition Inform	ation - None Defined				
	rmation - None Defined	1			
	mation - None Defined	Å			
Settlement			、 <i>.</i>		
		Remington/660/CF/I	3A		
Settlement	Release of Claims	Release Date	Reimbursement S	Cash ettlement	Reim. Cash Date Date APV APV
Replace TPA, check over and test at no charge					
_	Repair/Replacement Cost \$44	Repair/Replacement Date			
8/12/12 Dar Hinn "	T A yory dirty sticky	and rusty. Replace TPA,	algan and tact find u	ndor rocall	t n/a " ihi

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		<b>B.TRAVIS</b>

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9105&Type=... 8/13/2013

.

.

.

	Exam Date		8/9/2013
Examination	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4015	Improper Maintenance	
Barrel	Description		19.5" 243 WIN
	Date Code		KR
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
-	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	SCRATCHES, MARS, DENTS
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Lift	Select	.005
Sear	Notch	Slightly Worn; Functioning	
	<u></u>	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,STICKY,RUSTY WILL FOLLOW DOWN
	Pull	Select	8#
	Altered	False	SEALANT INCONCLUSIVE
	Sub-Assembly	Other Remington	

## Service Request

## Remington Service PO Box 700

Madison, NC 27025-0700



## www.Remington.com

KR S/W Parts and Repairs: P:800-243-9700/F:336-548-7801 84 This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN. °005

Service Request Number Serial Number SR00057448 105809	r / Description	9105	Date of Request: Date Printed:	07/24/2013 07/24/2013
Model 660 Ce	nter Fire		Date Frinted:	0//24/2013
Customer: JACOB BROTHERS		Destination: Arms Services	·	
1345 BOWERS BRIDGE ROAD MANCHESTER, PA 17345 US		14 Hoefler Ave Ilion, NY 1335	7 US	•
Email:		Email:		
Your request for service on the item(s) will be ev	aluated by our repairman to	determine if it is covered under our warranty p	olicy. If it is your firearm	will be repaired and
returned. If not, you will be contacted with an es	stimate before work is perfor	med.		
				1
Reason For Return				
M240 - BOLT LOCK SAFETY MODIFIC	CATION			
	······································			
Service Request Section Customer stated the rifle has fired several ti	me as the bolt is closed.	en en ser an andre en el de ser en de se En en		el de la companya de
	·			
Parts And Service Details	Nejstis as Period (			
Material Type Descriptio		Qty Warranty Needed	Price	Disc Amount
₿1 <b>05809</b>				
			NECEI	VE
) Model: 660			2	21.00
			AUG 12	2013 2
			BY:	
RE0031	/3//			
		TA weared	into stick	is pusty.
			h ( m h h h h h h h h h h h h h h h h h	t fine
		T.A. VERYd Replace TPH, und. peca	IL AT N/C	FIEL
		1	#230185	
THE R NOT AN INVOICE This is a mer action	to to ronair recondition	replace the item(s)	Sub Tatala	00
THIS IS NOT AN INVOICE. This is a pre-estimate being sent based on the conversation with our rep		epiace die neu(s)	Sub Total: Est Sales Tax:	.00 .00
			Grand Total:	\$.00











