Remington Arms Co., Inc. **Product Service**

Legal Case #:9412 Case Information RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 11/4/2013 11/5/2013 11/5/2013 326324 Customer Information City State Zip Age Type Business First Name Last Name Street Contact H 504-319-6301 Schindler 565 Lynnmade Ave Gretna LA 70056 Incident John E jschindler@glytech.com Incident Information Repair Medical Medical Claims Codes Est. **Treatment** Status ΡI Could Not Duplicate PD Cause:4038 Concern Unknown Unexplained Discharge - No Unexplained Discharge - No Mention of Safety Postion Concern:1025 Mention of Safety Position \mathbf{C} Per SR00064679 Service Request Section, "Customer states the rifle discharged when it was bumped without touching the trigger breaking the stock." jbi Firearm Information Model/Ga. SKU Mfg. DOM Type Serial Bbl. CF/BA 710/270 WIN 27408 71277640 LA 2/6/2006 2:42:57 AM Remington Date Purchased Where Purchased Accessories Original Owner ACADEMY CORP SCOPE BASE CONCERN: DISCHARGED WHEN BUMPED Ammunition Information - None Defined Other Products Information - None Defined Settlement Remington/710/CF/BA Reim. Cash Cash Release of Claims Settlement Release Date Reimbursement Date Date Settlement APV APV Replace trigger, check over and test fire at 50% discount Repair/Replacement Repair/Replacement Cost 11/6/13: Per Ilion, "could not duplicate concern. Trigger assembly and action dirty. Debris on and around sear. Can offer to replace trigger assembly, check over, and test fire at 1/2 cost. Replace with a used M/770 stock in good condition at no charge." jbi 11/8/13: I called John Schindler and he approved quote with a credit card. jbi Examination[Remington/CF/BA]

http://cps03sp01.remington.com:99/Remington PSA/PrintDisplay.aspx?ID=9412&Type=... 11/8/2013

PrintDisplay Page 2 of 3

Sub-Part	Code	Comment					
Examiner]	B.TRAVIS					
Exam Date]	11/5/2013					
Product Type]	RF					
Action Type]	A					
Assigned To		S.NICHOLS					
4038	Could Not Duplicate Concern						
Description		22" 270 WIN					
Date Code]	LA					
Bore Plugged	False						
Bulged	False						
Fired	False						
Fired while Obstructed							
Muzzle/Crown Condition	Slightly Worn; Functioning						
Firing Pin	Slightly Worn; Functioning						
Shroud	Slightly Worn; Functioning						
Face	Slightly Worn; Functioning						
Handle	Slightly Worn; Functioning						
Stop	Slightly Worn; Functioning						
Condition	Slightly Worn; Functioning						
Cut Condition	Slightly Worn; Functioning						
Ext/Eject Test	False						
Block Condition	Select						
Lug Condition	Slightly Worn; Functioning						
Notch Condition	Select						
Condition	Select						
Box Condition	Missing						
Exterior Condition	Slightly Worn; Functioning	DIRTY,RUSTY CHAMBER RUSTY DIBRIS ON AND AROUND SEAR					
Stock Condition	Abused; Not Functioning	TRIG GUARD BROKEN					
Fore End Condition	Select						
Condition	Slightly Worn; Functioning						
Bulged	False	7					
	Examiner Exam Date Product Type Action Type Assigned To 4038 Description Date Code Bore Plugged Bulged Fired Fired while Obstructed Muzzle/Crown Condition Firing Pin Shroud Face Handle Stop Condition Cut Condition Ext/Eject Test Block Condition Lug Condition Condition Exterior Condition Exterior Condition Stock Condition Fore End Condition	Exam Date Product Type Assigned To 4038 Could Not Duplicate Concern Description Date Code Bore Plugged False Fired Fired False Fired While Obstructed Muzzle/Crown Slightly Worn; Functioning Fring Pin Firing Pin Slightly Worn; Functioning Shroud Face Slightly Worn; Functioning Face Slightly Worn; Functioning Face Slightly Worn; Functioning Condition Slightly Worn; Functioning Slightly Worn; Functioning Slightly Worn; Functioning Slightly Worn; Functioning Condition Slightly Worn; Functioning Slightly Worn; Functioning Cut Condition Slightly Worn; Functioning Ext/Eject Test False Block Condition Slightly Worn; Functioning Ext/Eject Test False Block Condition Slightly Worn; Functioning Extroin Condition Select Condition Slightly Worn; Functioning Notch Condition Select Condition Slightly Worn; Functioning Notch Condition Select Condition Slightly Worn; Functioning Notch Condition Select Condition Slightly Worn; Functioning Fore End Condition Select Soudition Slightly Worn; Functioning Fore End Condition Select Soudition Slightly Worn; Functioning Fore End Condition Select Soudition Slightly Worn; Functioning					

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9412&Type=... 11/8/2013

Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
Sear	Lift	Select	N/A
	Notch Slightly Worn; Functioning		
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn, Functioning	
	Pull	Select	5.5#
	Altered	False	
	Sub-Assembly	Other Remington]

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9412&Type=... 11/8/2013

Quotation

Remington Service PO Box 700

Madison, NC 27025-0700

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number RE00326324	712	71277640 Estin						re Received: 11/04/2013 imate Date: 11/05/2013			
	Mod	del 710 RIFLE Caliber: 270	WIN				Date P	rinted:	1 1/07/2	013	
Customer: Return To: JOHN SCHINDLER 565 LYNNMADE AVE GRETNA, LA 70056 US Return To: JOHN SCHINDLER 565 LYNNMADE AV 6765 LYNNMADE AV 6765 GRETNA, LA 70056 US					DE AVE						
Please Circle One											
VISA MC	DISCOVER	Card No PO N				Ex	p.Date				
Open Account	i: R	PO I	Number:								
Approval Signatur	re:						Date:				
Daytime Phone	e: ()		Time to	o Call:							
Daytime Phone: () Time to Call: If you desire any change, please use the reverse side for your comments and mark this box.											
		DUCT SERVICE FOR INSPI CHECKS ON TRIGGER AS	ECTION	Poun M123		WARD TO PRO	DUCT SEI	RVICE FOR	INSPE	CTION	
	Technician Comments could not duplicate concern trigger assembly and action dirty debris on and around sear can offer to replace trigger assembly check over and test fire										
		ger assembly and action dirty. 4/770 stock in good condition		around	sear.can c	offer to replace	trigger asse	mbly,check	over and	l test fire	
		FIMATE (note: C.O.D./Ship	•	dling (charges a	re NOT Includ	led in this	Quote.)			
Material	Type	Description			Qty Needed	Warranty	Qty From Inv	Price	Disc	Amount	
F301265 4000114 4000119	Part Service Service	710 REC. INSERT ASSB. GR-SHIPPING & HANDLI'GR-TEST		AIR)	1 1 1	Billable Billable Billable	1 1 1	60.00 17.00 23.00	0	30.00 17.00 11.50	
								sb Total:		58.50 2.34	
								t Sales Tax:		2.34	
							G	rand Total:		\$60.84	



71277640 Model: 710 RF00326324

PECEIVE Nov 0 6 2013

BY: -----

could not duplicate concern.

T.A. + Act. dunky CANOFLER

to My. T.A. check over + 705

AT 1/2 cost. Mp. W/ New

Style Stp. At. N/c Green

Bench.

Q









