PrintDisplay Page 1 of 3

> Remington Arms Co., Inc. **Product Service** Legal Case #:9170

Case Information

Pre Lit Lit Obsolete RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** 9/5/2013 9/6/2013 320303 9/6/2013

Customer Information

Business First Name Last Name Street City State Zip Age Contact 40881 Recks Rd. Incident Centerville PA 16404 Robert Lerner H 814-827-3160 P.O. Box 41 40881 Recks Rd. Incident Robert Lerner Centerville PA 16404 H 814-827-3160 P.O. Box 41

Incident Information

Repair Medical Medical Claims Codes Est. Treatment Status

Ρl

PD

Altered Adjustments or Cause:4006

Components

Unknown

FSO, FBO, S **FSR**

Concern: 1028 Fired With Safe ON

C

Per letter from Robert Lerner, "gun fired once when ejection live ammo to empty gun, once when safety was disengaged, and twice when carrying gun with safety engaged. Please make it safe again." jbi

Firearm Information

Mfg. Remington Type

Model/Ga.

SKU

Serial Bbl.

DOM

CF/BA Where Purchased 721/3006 SPRG

N/A

287975 LZZ 2/1/1953

Date Purchased

Accessories

Original Owner

U

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/721/CF/BA

Settlement

Release of Claims

Release Date

Cash Reimbursement Settlement Reim. Cash Date Date

APV

APV

Replace trigger assembly, check over, and test fire under bolt lock program for \$20.00 +

shipping.

Repair/Replacement Repair/Replacement

\$25

Cost Date

9/9/13: Per Ilion, "trigger assembly dirty and set screws altered. Replace trigger assembly, check over and test fire

http://cps03sp01.remington.com:99/Remington PSA/PrintDisplay.aspx?ID=9170&Type=... 9/10/2013

PrintDisplay Page 2 of 3

under bolt lock program for \$20.00 + shipping." jbi 9/10/13: Called and left message for Robert Lerner to return my call. Received call from Robert Lerner, he approved quote with credit card. jbi

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		9/6/2013
	Product Type		RF
	Action Type]	A
	Assigned To]	S.NICHOLS
Cause	4006	Altered Adjustments or Components	
	Description		24" 3006 SPRG
	Date Code	·	LZZ
	Bore Plugged	False	
	Bulged	False	
Barrel	Fired	False]
	Fired while Obstructed].	
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Wom; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Wom; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Wom; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	MARS,SCRATCHES
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
RECEIVE	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	Select	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
	1 0313		

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9170&Type=... 9/10/2013

Feeding Test		False	
Trigger	Condition	Worn; Functioning	HAS EXCESSIVE ENGAGEMENT AND OVERTRAVEL
	Pull	Select	4.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	Other Remington	

Quotation

Remington Service PO Box 700

Madison, NC 27025-0700

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Numbe RE00320303	28	rial Number / Description 7975 Odel 721 : Center Pire Ca				Date Receiv Estimate Da Date Printe	ate: (09/05/2 09/06/2 09/09/2	013
Customer:	IVI	oder 721 Center The Ca	110ci . 30 =00	Retu	ırn To:	Date Frinte	u: (J7/U7/2	013
BUELLS CORNERS STORE 44467 BUELLS CORNERS ROAD SPARTANSBURG, PA 16434 US			BUELLS CORNERS STORE 44467 BUELLS CORNERS ROAD SPARTANSBURG, PA 16434 US						
Please Circle O	ne:								
VISA MO	C DISCOVEI unt: R	R Card No	PO Number:		Ex	o.Date			
Daytime Pho	one: ()		Time t	o Call:		_ Date:			
		please use the reverse sic	le for your comments	s and mark this b	oox				
Reported			Prol	olems Found				-	
	WARD TO PRO	DDUCT SERVICE FOR	INSPECTION	M123 - FOR		DUCT SERVIC Y MODIFICAT		INSPE	CTION
trigger assembly	y dirty and set s	crews altered, replace trip		Comments over and test fir	c under bolt loc	k program for \$2	20.00 + :	shippin	g
Material	Type ES	TIMATE (note: C.O.D Description	./Shipping and Han	dling Charges a Qty Needed	are NOT Includ Warranty		e.) Price	Disc	Amount
F202906 4000114 4000116 4000119	Part Service Service Service	40 SSA TRIG ASSB GR-SHIPPING & HAI GR-LABOR GR-TEST		PAIR) 1 20 1	Warranty Billable Billable Warranty	1 1 1	.00 7.00 1.00 .00	0 0 0	.00 17.00 20.00 .00
						Sub To Est Sal Grand	es Tax:		37.00 2.22 \$39.22

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

Service Request Number | Serial Number | Description

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number SR00059613	Serial Number / Description 287975	9179		Date of Request:	08/21/2013
	Model			Date Printed:	08/21/2013
Customer: ROBERT LERNER	O Box HI	' Des	tination: Arms Services		
40881 RECKS RD ρ CENTERVILLE, PA 1		·	14 Hoefler Ave Ilion, NY 13357 U	IS	
T1					
V	: itcm(s) will be evaluated by our repairman		37075	•	
rour request for service on the returned. If not, you will be co	enteri(s) will be evaluated by our repairman in intacted with an estimate before work is perf	onnou.)	
TA dink	1+ set screws alto	Moc	^{lel:} 721		
Pup. TPA, ch	1+ set screws afti uchoweners turid 20+ Q				
BUPLON -	20+ 0				
Reason For Return					
Reason For Return M240 - BOLT LOCK SA	FETY MODIFICATION	1.4	REUU	3203	03
			1 1 1		
					5 1470 ABRE
1 2	1 18 1 2 1		X		1
A A	1 2 2 3	8	3 3		
	7 9 9 1 3 4	9 1	0 2		
3	2 6 6 W	2 3	0 3	0	11.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.
\ \mathref{z}	3 1 3 3 3	9 3 7	200	3160	Disc Amount
		3 3	9 2 2	*	1
12 3	2 7 2 3	E 12. 12	3 2 0	\sim	·
12 3	E E B B B B B B B B B B B B B B B B B B	7 13 9	2 2 3	2	
2 4	2 2 3 1 1 9		7 2 3		
1 3	13 7 4 3	3 7 2	Le R	14	
1.3 19	五 3 多 4	8 H 121	of cat	80	
at 7	8 8 8 8 E	2 2	108		Į
1 3 7	7 4 4 9 8	27		Phone	
10 3		\$ 30		hor	
1'7 1	4 4 4 9 9 9	4		9	
				ECI	eiven
				SEP (9 2013
			•		0 2013
THIS IS NOT AN INVOICE. The being sent based on the conversa	nis is a pre-estimate to repair, recondition, or	replace the item(s)		Sub Protat:	
oeing sein based on the conversa	andi with our representative.			Est Sales Tax:	.00

\$.00

Grand Total:









