Remington Arms Co., Inc. Product Service Legal Case #:9055

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

315566 7/16/2013 7/22/2013 7/22/2013

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Incident Brady Bowthorte 601 West Adams Riverton WY 82501 H 307-856-2590

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ы

PD Cause: 4038 Could Not Duplicate Concern

Concern:1007 Fired on Safe Release

Unknown

C

S FSR

Per Service Request, wants safety modification. States gun fired when safety was taken off. jbi

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 700/3006 SPRG
 n/a
 A6722725
 LV 2/1/1979

Date Purchased Where Purchased Accessories Original Owner

UDISCO SALT LAKE CTY UT TWO PIECE BASE U

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Cash Settlement Release Date Reimbursement Settlement APV APV

Replace trigger assembly, clean and test fire under bolt lock program

Repair/Replacement Repair/Replacement Cost Date

\$42

7/23/13: Per Ilion, could not duplicate concern. Trigger assembly is very dirty, sticky, and parts work sluggish. Replace trigger assembly, clean and test fire under bolt lock program. jbi 7/24/13: Called customer with quote. He will call me back with cc information. jbi 7/25/13: Customer called and approved with credit card. jbi

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9055&Type=... 7/25/2013

	Exam Date		7/22/2013
Examination	Product Type	1	RF
	Action Type	1	A
	Assigned To	-	S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
	Description		22" 3006 SPRG
	Date Code		LV
	Bore Plugged	False	
	Bulged	False	
Barrel	Fired	False	
	Fired while Obstructed		_
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
-	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description]	BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Lift	Select	.010
		Slightly Worn;	

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9055&Type=... 7/25/2013

G	Notch	Functioning	
Sear	Toots	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY AND STICKY PARTS WORK SLUGGISH
	Pull	Select	4.5#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		TWO PIECE BASE

Quotation

Remington Service PO Box 700

Madison, NC 27025-0700

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number RE00315566		Serial Number / Description A6722725 Model 700 Center Fire Caliber: 30 -06 S	SPRG			Date Rec Estimate Date Pri	Date:	07/16/2 07/22/2 07/24/2	013
Customer: BRADY BOV 601 WEST AI RIVERTON,	DAMS			1	rn To: BRADY BOWTI 501 WEST ADA RIVERTON, W	MS	JS		
Please Circle One									
VISA MC					Exp.	Date		··	
Open Account	: R	PO Number:							
Daytime Phone	: ()	Time to Call: _	rk this h					
Reported M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION M240 - BOLT LOCK SAFETY MODIFICATION M125 - FORWARD TO PRODUCT SERVICE FOR INSPECTION M240 - BOLT LOCK SAFETY MODIFICATION									
Technician Comments could not duplicate concern. Trigger assembly is very dirty and sticky, parts work sluggish. Replace trigger assembly, clean and test fire under bolt lock program.									
Material	Туре	ESTIMATE (note: C.O.D./Shipping an Description		narges a Qty eeded	Warranty	d in this Q Qty From Inv	uote.) 🔀 Price	Disc	Amount
F305570B 4000114 4000116 4000119 4000294	Part Service Service Service Service	X-MARK PRO 700 TRIG ASSB REGR-SHIPPING & HANDLING (GUGR-LABOR) GR-TEST GR-CHECK TPA	N REPAIR)	1 1 20 1 1	Warranty Billable Billable Warranty Warranty	1 1 20 1 1	.00 17.00 1.00 .00 .00	0 0 0 0 0	.00 17.00 20.00 .00
						Est	Total: Sales Tax:		37.00 1.85 \$38.85

Service Request

Remington Service PO Box 700



Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number

Serial Number / Description

SR00045151

A6722725

Model R5772

Customer:

BRADY BOWTHORTE

601 WEST ADAMS RIVERTON, WY 82501 US

Date of Request:

02/13/2013

Printed:

02/14/2013

Destination:

Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email:

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M240 - BOLT LOCK SAFETY MODIFICATION

Service Request Section

The que misfired. wants safety modification/states gun fired when safety was taken off

Parts And Service Details

Material

Description

Qty Needed Warranty

Price Disc Amount

PECEIVE 1 jul 2 3 2013,

Could Not duplicate CONCERN T.A. IS very direly +Sticky. PARTS WORK Sluggish. Rup. TPA, cleAN+ TREST UND. BCP For 20+

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total:

.00 .00

Est Sales Tax:

Grand Total:

\$.00







