PrintDisplay Page 1 of 2

Remington Arms Co., Inc.

				Product Service								
Case Infor	ation			Legal Case #:8834								
RE# 308740	mation Date Op 4/22/20		Date Opened(PS) 4/23/2013	Date Closed 4/23/2013		Incid	ent Da	ite	Pre L	it Li	t	Obsolete
Customer l	Information											
Type	Business	First Name	Last Name	Street (City	State	Zip	Age			ntac	•
Incident		Darren	Clutter	1126 Station Rd P	alm	PA	18070)	Εd	H 215- llance@		4692 nail.com
Incident In	formation											
	Claims		Coo	les		Repair E	st. I	Medical	Treatm	ient	Med	ical Status
PI												
PD		Cau	ise:4038 Could N	lot Duplicate Concern				I Inl	known			
	d on safety rele	ase Cor	icern:1007 Fired or	Safe Release				Oili	MIOWII			
C												
5/1/13 Per	note on SR, fir	red as safety w	as pushed off.cm									
Firearm In	formation								-			
	Mfg.		Type	Model/Ga.		SK	Œ		Serial	Bbl	_	DOM
	mington	(CF/BA	700/270 WIN		n/			10309		-	5/1/1962
	Purchased	Wher	e Purchased	Accessories		Original	Owne	er				
						υ						
CONCERI	N: FSR											
Ammunitio	on Information	- None Define	ed.									
Other Prod	lucts Information	on - None Defi	ined									
Settlement												
				Remington/700/CF/BA	4							
	Settlement	Re	lease of Claims	Release Date	F	Reimburs	ement	Ca Settle	sh ment	Reim. AP		Cash Date APV
	ГРА, clean and M program pri											
		Rep	air/Replacement Cost	Repair/Replacemen Date	t							
			29.04	5/1/2013								
5/1/13 Per	Hion, could no	t duplicate cor	ncern. Trigger assm	dirty and sticky. Repla	ce T	PA, clear	and to	est at BL	SM pro	gram p	rice.c	m
Examination	on[Remington/	CF/BAI										

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		4/23/2013
Examination	Product Type		RF
	Action Type		A
	Assigned To		SNICHOLS
Cause	4038	Could Not Duplicate Concern	
	Description		20" 270 WIN
	Date Code		KJ
Barrel	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
			= <u></u>

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8834&Type=Case

5/1/2013

	Firing Pin	Slightly Worn; Functioning	
Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	MARS,DENTS
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
Salety	Function	Like new; Functioning	
	Lift	Select	.010
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tesis	False	
	Condition	Slightly Worn; Functioning	DIRTY,STICKY
Trigger	Pull	Select	2.5#
ı ugger	Altered	True	PULL SCREW ALTERED
	Sub-Assembly	M/700 Bolt Lock	

Service Request

Remington Service PO Box 700



Parts and Repairs: Pi800-243-9700 Fi335-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to innure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Madison, NC 27025-0700

7011 KJ5/62 1010 2.50

04 01/2013 Service Request Number Serial Number / Description Date of Request: 3R .6049464 Date Printed: 04/01/2013 19309 Destination: Customer: DARREN CLUTTER Arms Services 1136 STATION RDAD 14 Hoeiler Ave PALMI PA 18070 US Hien, NY 13357 US Email: čllance @hotmail.com -Vour regoest for service on the item(s) will be evaluated by our regainmento determine if it is covered under our wattenty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed 215-828-4692 Reason For Return M240 - BOLT LOCK SAFETY MODIFICATION Service Request Section Per consumer, fired as safety was pushed off. Parts And Service Details Material Type Description Warranty Price Disc Amount

10309 Model:

THIS IS NOT AN ENVOICE. This is a pre-estimate to repair, recondition, or replace the

couldnot dup. concenu T.A. dinly & sticky, hip. BUP GON 20 +

> Sub Total: Est Sales Tax:

.00 .00

Grand Total:

\$.00







