PrintDisplay Page 1 of 3

Remington Arms Co., Inc.
Product Service
Legal Case #:9062

			Pr	oduct Service							
			Leg	al Case #:9062							
Case Information											
RE# Date (Opened	Date Opened	l(PS)	Date Closed	Incid	Incident Date			Lit	Ob	solete
316104 7/23	104 7/23/2013 7/24/201		3 7/24/2013								
Customer Informat	tion										
Type Business	First Name	Last Name	S	Street	Cit	y	State	Zip A	ge	Con	tact
Incident	Rodney	Fels	328 Mt. Pleasant Cemetery Rd		Chattahoochee FL		32324 H		1 850-663- 5757		
Incident	Rodney	Fels		it. Pleasant etery Rd	Chattahoochee FL		FL	32324		H 850-663- 5757	
Incident Information	on										
Claims			Codes			-	pair st.	Medio Treatn		_	edical tatus
PI											
PD		Cause:40	15 Im	proper Mainten	ance						
S Unexplained I	Discharge -	No C	unas Un	explained Discl	harge - No	0		Unkno	wn		
Mention of Sa	fety Postion	n Concern.	Me	ention of Safety	Position						
С											
Per Service Reques	st, "Consun	ner states the ri	fle went	off". Per Ilion,	trigger as	ssembly	is di	irty, sticky	, and	rusty	, jbi
Firearm Information	on					*					
Mfg.	Т	/pe		Model/Ga.		SK	Π	Serial	Rb'	і. Т	OM
Remington	_	/BA	700/308 WIN			n/a	_	A65822			
Date						Origi	-	1103022.	70 710	, ,,	0.1770
Purchased	Where P	re Purchased		Accessories		Own					
	J WILSON	CO CAPE	TWO PIECE			U					
		EAU MO	BASE, COMPASS IN STK			U					
CONCERN:RIFLE	E WENT O	FF									
Ammunition Inform	mation M	one Defined	-								
Other Products Info											
	ormation -	None Defined									
Settlement				/= 0 0 / O= 1=							
			Remn	ngton/700/CF/B	SA						~ ·
Settlement	Rel	ease of Claims	I	Release Date	Reimb	ursem	ent s	Cash Settlemen	, Da	im. ate PV	Cash Date APV
Replace trigger assembly, clean, a test fire under bolt program for \$20.0 shipping.	and lock								,		
	Rena	ir/Replacemer	it Rens	ir/Replacemen	nt						

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9062&Type=... 7/25/2013

Date

Repair/Replacement Repair/Replacement

Cost

\$27

PrintDisplay Page 2 of 3

7/25/13: Per Ilion, replace trigger assembly, clean, and test fire under bolt lock program for \$20.00 + shipping. Called customer with quote and he approved with credit card. jbi

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
Examination	Exam Date		7/24/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4015	Improper Maintenance	
	Description		22" 308 WIN
	Date Code		AQ
	Bore Plugged	False	
	Bulged	False	
Barrel	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select]
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	HAD BEEN REFINISHED
	Fore End	Select	

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9062&Type=... 7/25/2013

	Condition		
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Lift	Select	.010
Sear	Notch Slightly Worn; Functioning		
	T	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Not Functioning	DIRTY,STICKY,RUSTY PARTS WORK SLUGGISH WILL FOLLOW DOWN
Trigger	Pull	Select	5#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE, COMPASS IN STK

Quotation

Remington Service PO Box 700

Madison, NC 27025-0700

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

RE00316104	E00316104 A6582256					Estimate l Date Prin	Date:	07/23/2 07/24/2 07/25/2	.013		
Customer: RODNEY FELS 328 MT PLEASANT CEMETERY ROAD CHATTAHOOCHEE, FL 32324 US				Return To: RODNEY FELS 328 MT PLEASANT CEMETERY ROAD CHATTAHOOCHEE, FL 32324 US							
Please Circle One VISA MC	DISCOVER	Card No	PO Number:		Exp	o.Date					
Approval Signatu	re:					Date:					
Daytime Phon	e: ()	olease use the reverse s	Time	to Call:							
Reported M123 - FORW	ARD TO PRO LOCK SAFET	DUCT SERVICE FOR Y MODIFICATION	INSPECTION	Found M123 - FOR M238 - CLE M240 - BOL	WARD TO PRO AN & INSPECT I LOCK SAFET	DUCT SERV (SAFETY PR Y MODIFICA	ICE FOR OGRAM ATION				
trigger assembly,	dirty,sticky and	l rusty replace trigger a	ssembly, clean and te	est fire under bolt	lock program fo	or \$20.00 + shi	pping				
Material	Type	TIMATE (note: C.O.) Description	D./Shipping and Ha	ndling Charges a Qty Needed	Warranty	ed in this Qu Qty From Inv	Price	Disc	Amount		
F305570B 4000114 4000116 4000119	Part Service Service Service	X-MARK PRO 700 T GR-SHIPPING & HA GR-LABOR GR-TEST			Warranty Billable Billable Warranty	1 1 20 1	.00 17.00 1.00 .00	0 0 0	.00 17.00 20.00 .00		
-						Sub 7 Est S	Fotal: ales Tax:		37.00 2.22		
						Gran	d Total:		\$39.22		

Service Request

Remington Service PO Box 700

07/08/2013

07/08/2013

Date of Request:

Printed:

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number | Serial Number | Description

SR00056336

A6582256

Model R5774

Customer:

RODNEY FELS

328 MT PLEASANT CEMETERY ROAD CHATTAHOOCHEE, FL 32324 US

Destination: Arms Services 14 Hoefler Ave

Ilion, NY 13357 US

Email:

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

M240 - BOLT LOCK SAFETY MODIFICATION

Service Request Section

Consumer states the rifle went off

Parts And Service Details

Material

Description

Qty Needed Warranty

Price

Disc Amount

A6582256

Model:



T.A. dinty, sticky, + musty.

My. TPA, cleana Test unb.

BLP for zo +

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

.00 .00

Est Sales Tax: Grand Total:

\$.00







