Remington Arms Co., Inc. Product Service Legal Case #:9392

Case	Informa	ition

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 326011 10/31/2013 11/1/2013 11/1/2013

Customer Information

First Last Type Business Street City State Zip Age Contact Name Name 7941 W H 559-651-2525 Goshen Incident Riley Iden Visalia CA 93291 Ε easleysgunshop@hotmail.com Suite A

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PI PD

Cause: 4006 Altered Adjustments or Components

Unknown

S FSR Concern:1007 Fired on Safe Release

C

Per SR00064106 Service Request Section, "Consumer states that when loaded & take safety off the firearm discharges without pulling trigger." jbi

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM CF/BA 700/223 REM Remington 27490 E6237250 LQ 2/1/1996 Date **Original** Where Purchased Accessories Purchased Owner **GRICE**

WHOLESALE

AFT MKT STK,TWO PIECE BASE

U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Date Settlement Settlement

Offer to replace trigger assembly, check over, and test at 50% discount

Repair/Replacement Cost Repair/Replacement Date

11/5/13: Per Ilion, "action and trigger assembly very dirty and rusty, set screws altered. Can offer to replace trigger assembly, check over, and test fire at 1/2 cost." jbi 11/6/13: I called Riley Iden with quote. He said he will call back with credit card. jbi 11/15/13: I received call from Riley Iden, he approved quote with credit card. jbi

http://cps03sp01.remington.com:99/Remington PSA/PrintDisplay.aspx?ID=9392&Type... 11/15/2013

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Соттепт
	Examiner		B.TRAVIS
Examination	Exam Date		11/1/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4006	Altered Adjustments or Components	IMPROPER MAINTENENCE
	Description		20" 223 REM HB
	Date Code		LQ
	Bore Plugged	False	
	Bulged	False	
Barrel	Fired	False	
	Fired while Obstructed		,
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	VERY DIRTY/RUSTY
	Shroud	Slightly Worn; Functioning	VERY DIRTY/RUSTY
Bolt	Face	Slightly Worn; Functioning	VERY DIRTY/RUSTY
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking		Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Functioning	VERY DIRTY,RUSTY
	Stock Condition	Select	AFT MKT
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
		False	

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9392&Type... 11/15/2013

Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
Sear	Lift	Select	.011
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	VERY DIRTY,PARTS SLUGGISH AND BIND WILL FOLLOW DOWN
	Pull	Select	3.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		AFT MKT STK,TWO PIECE BASE

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9392&Type... 11/15/2013

Quotation

Remington Service PO Box 700

Estimating Report Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number RE00326011		rial Number / Description				eceivea: te Date:	11/01/2	
KI200320011					Date P		11/06/2	
				***** T- *		· •		
Customer: RILEY IDEN			Ke	turn To: RILEY IDEN				
7941 W GOSI				7941 W GOSHE	N			
SUITE A				SUITE A				
VISALIA, CA	4 93291 US			VISALIA, CA 9	3291 US			
Please Circle One								
		Card No.						
Open Account	t: R	PO Number:						
Approval Signatur	ro·				Data			
Daytime Phone	e: ()	Time to Ca	ill:		Date			
		please use the reverse side for your comments and	i mark this	s box.				
	,,	Problem					····	
Reported			und					
		DUCT SERVICE FOR INSPECTION M ENGAGE PROPERLY	123 - FO	RWARD TO PROI	OUCT SEF	RVICE FOR	. INSPE	CTION
141040 - SAFET	I DOES NOI	ENGAGETROFERET						
action and triager	accombly yes	Technician Co y dirty and rusty, set screws altered can offer to re		er accombly check	over and t	act fire at 1	/2 cost	
action and trigger	assembly very	y diffy and fasty, set screws aftered can offer to re	prace trigg	ger assembly, check	Over and t	est inc at i	2 6031.	
	ES	TIMATE (note: C.O.D./Shipping and Handlin	g Charge	s are NOT Include	d in this (Quote.)		
Material	Type	Description	Qty	Warranty	Qty	Price	Disc	Amount
FRACEROR	ъ.	WALLEY DROUGHT TRUE AGED BY DI AGE	Needed		From Inv		F.0	40.50
F305570B 4000114	Part Service	X-MARK PRO 700 TRIG ASSB RH BLACK GR-SHIPPING & HANDLING (GUN REPAIR		Billable Billable	1 1	97.00 17.00		48.50 17.00
4000119	Service	GR-TEST	ī	Billable	ī	23.00		11.50
	,							
					Su	ıb Total:		77.00
						t Sales Tax	:	2.91
					_			A70 04
l .					Gı	rand Total:		\$79.91

StrmReparMain - FGI Repart File Add Repart Estimate Repair Excedite Répair Inquiry Repair Tools	CSR Tools Reports Table Maintenance System	F • * • • • • • • • • • • • • • • • • •		
	and refer to the contract	The first Charles and A		
	FormEnglish Repair Inquiry V. Repair Market (RE00326011 Serial DE23264 Model Tito Riffu	CHANGE THE PARTY OF THE PARTY O	A STATE OF THE STA	
	Voits Record 93	32 Repositives: New 1810/2013 4-16 OS FRE		
	Customer	FALEY (IDEN FALEY WOODSHEN SAFEE FALEY FA	an	20 2/9
	lictar inter-	Accessories Received	All the second s	3.5
	Repair Search	Refrach Close		
Property of the control of the contr		The state of the s	a state of the sta	15 5 1 3 A
Transhwi-I, M-Stred	nf approblem	OMOSCHYTT	Friday, Noor), data	354.7 AAM
	制造 经营业		. 1	- B □ 40 ±10/2013

E6237250

Model: 700



RE0032601

PECEIVE Nov o 5 2013

BY:-----

ACT. A. Verydinty busty Set Screws Alt. CANORher TO Mp. T.A. chellower & Test At 1/2 cost.

(२













