

CEIVING AND ESTIMATING REPORT					:	:	R 97-03691	
CUSTOM	ER ORDER NO.		AL MTTA	CK KAST				
NECEMED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRA			
2/83/97	02/10/9	7 NC 8-86	<u> </u>		796	30-06	ADL	·
SORIS	W/STUDS		BASE	L/SIGHTS	<u>V.</u>			
iOM:					SHIP TO:			
, , , , , , , , , , , , , , , , , , , ,	– *	a.		٦	□.": }			
	UHIT	E, DANNY R			WHITE,	DANNY	R	
	7325	ROPER TUNNE	L RD	any pao 2 mag may			NNEL RD	AL
•	TRUS	SVILLE	AL	35173	TRUSSY	LLLE	351	
							, -	. –
	L	ACCOUNT NUMBER N/C	CUST	NO:161785 C.C	PROM. DATE	ESTIMATED	O VIA	
COUNT NUMBER		ACCOUNT NUMBER WC	WRITE _	1	W. DATE			29
N CONOTION							REPAIR CHARG	
NEW NEW					1		EXCISE	
LIGHTLY WOR					•		TAX	
	`				*		INSURANCE	
*					÷		UPS	
VERY WORN							PARCEL POST	
UNREPAIRABLE	E		•				TOTAL	
MARRED							TOTAL	
JSTOMER CON	NCERN	AMMO FUN	CTION FI	NISH ACCURACY	Y FIT	IN	SPECT	
CLE		В,	-					
IĞGER GROUF)	: B2 /			1, 17	! F1		
LT ASSY.		FINEI	asken .	seft was no	eliased	F2		
RREL ASSY.		34/		2 170		1831	, (
C. ASSY.	e, I	Clear	red and	oiled - so	be il si	till h	ara	
DOD		do to	the off	. 103		F5		
TAL			12					
N FAULT	malle	to duply	who All	troner amen	in as 1	and.	This on	·N
روعو	'a sis	1 magac	50/000	Sound Late	he of as	ed un	and so In	1.6
27	H board	This I	mit faki	Louis NALL	Win ch	e zine	Exchan	CO.
The state of	c acso	May The	r	CLUWA MAKE	VAIII ICIU	surg.	cronwi	<i>jc.</i>
120	7 7309	as 445						
•	- <u> </u>							
					••-			
							,	
TS	-f	in heer		COMMENTS FALL	sull mes	susad	16-605	185
TS	to	vý Assy.		COMMENTS THE	zull mee	meed	4 405	1.135
TS	ti	ug Assy.		COMMENTS fuic	sull mea	suced	4 105	435
TS	to	ug Assy.		COMMENTS THE	sull mea	suced	4105	1.85
TS	ta	ng 1559.		comments fuic	ruhmer 1. A. h.	suced . Hon	4105	135
TS	ti	eig Assy.		COMMENTS fui. as rede. Ruston y	sult mex bolt plu	suced i Hores	4 to 5.	1.135
TS	tr	ug Assy.		Ruston y	holt pluy	ured Hole	4 +05	185
TS	ta	rig Assy.		Ruston y Adjust les	sull med bolt plug ryth of	suced i Holes tront	4 to 5 uds take dow	1.135 VM 5.07
TS		rig 1959.		Ruston y Adjust lin	rull med belt pluy ryth of	suced i Holes Front	4 to 5 Uds Take doe	1.135 m 500
TS	to	eig Assy.		COMMENTS fuic os nebal Ruston y Adjust les	sult see bolt pluy ryth of	suced Hele Front	4 to 5 uds take dow	4B5 M SOU
TS	Tr.	rý Assy.		COMMENTS Turing Os neder	sult med holt plug right of	suced Hille Front	4 to 5 Uds Take dow	1135 vn 500
TS	The state of the s	rig Assy.		Ruston y	sull med bolt plug ngth of	suced i Holli Front	4 to 5 Uds Take don	135 m 500
TS	The state of the s	11g A559.		Ruston y Adjust ly REPAIRMAN 2900F	hoft plug	suced i Hole Front	4 fo 5 Will Take don	LBS
TS		ug Assy.		REPAIRMAN 200F	U	suced front		
TS		rý Assy.		Ruston y	CLEAN CLEAN	TEST DATE	TARGET DATE	PATTER DATE

Danny R. White 7325 Roper Tunnel Rd. Trussville Al 35173 (205) 655-9421 home (205) 558-5991 work

Dear Remington Arms,

I would like to take this opportunity to report to you a problem I experienced with my Remington Model 700 ADL 30-06. The problem was in the safety/trigger assembly. The rifle is approximately 6 years old.

On monday 01/20/97 I was deer hunting and was trying to load my rifle. listed below are the events:

- 1. I loaded 4 rounds in the rifle and chambered a round.
- 2. I tried to slide the safety to safe. I could not move the lever.
- 3. I unloaded the rifle and continued to work with the safety lever.
- 4. I removed the bolt, inspected the bolt and replaced the bolt.
- √ 5. I tried again to slide the safety lever to safe. It moved this time.
 - 6. Since I was having problems, I tried to move the lever to fire.
 - 7. The lever would not move to fire. After continuing to try to move the lever to fire, the lever did move, but the gun discharged in the process. I was lucky to have removed the cartridges.
 - 8. I replaced the rifle in its case and went home.
 - After getting home, I cleaned the safety/trigger assembly with Remington Bore and Action cleaner and sprayed RemOil in the action. This seemed to help some, but it is still very difficult to move the safety lever.

I want to thank you in advance for resolving the problem to both Remington's and my satisfaction. Safety is something I observe and practice. This incident could have caused damage or injury had I not been very careful when I noticed the rifle was not working properly.

Sincerely,

Danny R. White

RIFIE SERIAL # BEP06203