Guns 100 50 10 1 Dem's DFU Avg. Date 127 0 1 23 17 297 2.3 1.9 2.1 50 DEMERIT ITEMS (1)	A 1 11	no boltlock		
Week Ending 3/12/82 Total Demerit Category Total Week 4 Wks. Yr. t 127 0 1 23 17 297 2.3 1.9 2.1 50 DEMERIT ITEMS (1)	the MI	PINTSHED G	JN QUALITY	
Guns 100 50 10 1 Dem's DPU Avg. Date 127 0 1 23 17 297 2.3 1.9 2.1 50 DEMERIT ITEMS (1)			ng 3/12/82	
127 0 1 23 17 297 2.3 1.9 2.1 50 DEMERIT ITEMS (1)				
M/700 1. Wrong instruction folder (old style safe; new style folder). 10 DEMERIT ITEMS (23) 18.1% Defective 16.2% - 4 Wks. Avg. 19.0% - Yr. to I NUMBER 18.1% Defective 16.2% - 4 Wks. Avg. 19.0% - Yr. to I NUMBER 12 MG 12 MG 12 MG M/870 1. White recoil pad spacer cracked 2. Eulge at muzzle end of Barrel 3. Ejector spring cracked M/1100 Same(1. Excess steel margin Stock to Receiver, (excess wood margin Stock to Receiver) 2 Gun(2. Fore End peeling 3. Dirty recoil pad 4. Excess wood margin Stock to Receiver 2 5. Barrel pitted on side 6. Feed latch fell out 2 7. Excess wood margin Stock to Receiver 2 8. Excess wood margin Stock to Receiver 2 9. Excess steel margin Stock to Receiver 3 9. Excess steel margin Stock to Receiver 3 9. Excess steel margin Stock to Receiver 3 9. Orange peel on Stock 3	127			
style folder). 10 DEMERIT ITEMS (23) 18.1% Defective 16.2% - 4 Wks. Avg. 19.0% - Yr. to I NUMBER 12 MG 18.1% Defective 16.2% - 4 Wks. Avg. 19.0% - Yr. to I NUMBER 12 MG 12 MG M/870 1. White recoil pad spacer cracked 2. Bulge at muzzle end of Barrel 3. Ejector spring cracked M/1100 Same(1. Excess steel margin Stock to Receiver, (excess wood margin Stock to Receiver 2 Gun(2. Fore End peeling 3. Dirty recoil pad 4. Excess wood margin Stock to Receiver 2 5. Barrel pitted on side 6. Feed latch fell out 2 7. Excess wood margin Stock to Receiver, excess steel margin Stock to Receiver 2 8. Excess wood margin Stock to Receiver 2 9. Excess steel margin Stock to Receiver 2 9. Excess steel margin Stock to Receiver 2 9. Excess steel margin Stock to Receiver 2 9. Orange peel on Stock 3	50 DEMERIT I	TEMS (1)		
18.1% Defective 16.2% - 4 Wks. Avg. 19.0% - Yr. to I NUMBER 12 MC M/870 1. White recoil pad spacer cracked 2. Bulge at muzzle end of Barrel 3. Ejector spring cracked M/1100 Same(1. Excess steel margin Stock to Receiver, excess wood margin Stock to Receiver 2 Gun(2. Fore End peeling 3. Dirty recoil pad 4. Excess wood margin Stock to Receiver 2 5. Barrel pitted on side 6. Feed latch fell out 2 2 7. Excess wood margin Stock to Receiver, excess steel margin Stock to Receiver 2 2 8. Excess wood margin Stock to Receiver 2 2 9. Excess steel margin Stock to Receiver 2 2 9. Excess steel margin Stock to Receiver 3 2 9. Excess steel margin Stock to Receiver 3 2 9. Excess steel margin Stock to Receiver 3 3 10. Poor finish on grip cap 3 3 3 11. Poor finish on grip cap 3 3 3 12. Orange peel on Stock 3 3 3 3 13. Dirty recoil pad 4. Excess wood margin Stock to Receiver 3 3 <	<u>M/700</u>		er (old style saf	e; new
M/870 1. White recoil pad spacer cracked 2. Bulge at muzzle end of Barrel 3. Ejector spring cracked M/1100 Same(1. Excess steel margin Stock to Receiver, (excess wood margin Stock to Receiver) Gun(2. Fore End peeling 3. Dirty recoil pad 4. Excess wood margin Stock to Receiver 5. Barrel pitted on side 6. Feed latch fell out 7. Excess wood margin Stock to Receiver, excess steel margin Stock to Receiver 8. Excess wood margin Stock to Receiver 9. Excess steel margin Stock to Receiver 9. Excess get margin Stock to Receiver 1. Poor finish on grip cap 2. Orange peel on Stock	10 DEMERIT 1	<u></u>	######################################	Alexandra and a second a second a
M/870 1. White recoil pad spacer cracked 2. Bulge at muzzle end of Barrel 3. Ejector spring cracked M/1100 Same(1. Excess steel margin Stock to Receiver, excess wood margin Stock to Receiver Gun(2. Fore End peeling 3. Dirty recoil pad 4. Excess wood margin Stock to Receiver 5. Barrel pitted on side 6. Feed latch fell out 7. Excess wood margin Stock to Receiver, excess steel margin Stock to Receiver 8. Excess wood margin Stock to Receiver 9. Excess steel margin Stock to Receiver 9. Excess steel margin Stock to Receiver 9. Excess steel margin Stock to Receiver 1. Poor finish on grip cap 2. Orange peel on Stock	18.19	Defective 16.2% - 4	Wks. Avg.	19.0% - Yr. to Da
M/870 1. White recoil pad spacer cracked 2. Eulge at muzzle end of Barrel 3. Ejector spring cracked M/1100 Same(1. Excess steel margin Stock to Receiver, excess wood margin Stock to Receiver Gun(2. Fore End peeling 3. Dirty recoil pad 4. Excess wood margin Stock to Receiver 5. Barrel pitted on side 6. Feed latch fell out 7. Excess wood margin Stock to Receiver 8. Excess wood margin Stock to Receiver 9. Excess steel margin Stock to Receiver 1. Poor finish on grip cap 2. Orange peel on Stock		~ .		NUMBER
2. Bulge at muzzle end of Barrel 3. Ejector spring cracked M/1100 Same(1. Excess steel margin Stock to Receiver, excess wood margin Stock to Receiver Gun(2. Fore End peeling 3. Dirty recoil pad 4. Excess wood margin Stock to Receiver 5. Barrel pitted on side 6. Feed latch fell out 7. Excess wood margin Stock to Receiver, excess steel margin Stock to Receiver 8. Excess wood margin Stock to Receiver 9. Excess steel margin Stock to Receiver 9. Excess steel margin Stock to Receiver 9. Excess steel margin Stock to Receiver 1. Poor finish on grip cap 2. Orange peel on Stock	M/870	1. White recoil pad space	r crackeđ	
M/1100 Same(1. Excess steel margin Stock to Receiver, excess wood margin Stock to Receiver 2 Gun(2. Fore End peeling 3 Joirty recoil pad 4 Excess wood margin Stock to Receiver 2 S. Barrel pitted on side 2 6. Feed latch fell out 2 7. Excess wood margin Stock to Receiver, excess steel margin Stock to Receiver 2 8. Excess wood margin Stock to Receiver 2 9. Excess steel margin Stock to Receiver 3 1. Poor finish on grip cap 3 2. Orange peel on Stock 3				
(excess wood margin Stock to Receiver 2 Gun(2. Fore End peeling 3 3. Dirty recoil pad 4 4. Excess wood margin Stock to Receiver 2 5. Barrel pitted on side 2 6. Feed latch fell out 2 7. Excess wood margin Stock to Receiver, excess steel margin Stock to Receiver 2 8. Excess wood margin Stock to Receiver 2 9. Excess steel margin Stock to Receiver 3 M/700 1. Poor finish on grip cap 3 2. Orange peel on Stock Stock Stock		3. Ejector spring cracked		(
3. Dirty recoil pad 4. Excess wood margin Stock to Receiver 5. Barrel pitted on side 6. Feed latch fell out 7. Excess wood margin Stock to Receiver, excess steel margin Stock to Receiver 8. Excess wood margin Stock to Receiver 9. Excess steel margin Stock to Receiver 9. Excess steel margin Stock to Receiver 9. Excess steel margin Stock to Receiver 1. Poor finish on grip cap 2. Orange peel on Stock	<u>M/1100</u> Same	1. Excess steel margin St excess wood margin Sto	ock to Receiver, ck to Receiver	25
4. Excess wood margin Stock to Receiver 2 5. Barrel pitted on side 6. Feed latch fell out 2 6. Feed latch fell out 2 7. Excess wood margin Stock to Receiver, excess steel margin Stock to Receiver 2 8. Excess wood margin Stock to Receiver 2 9. Excess steel margin Stock to Receiver 2 9. Excess steel margin Stock to Receiver 2 9. Excess steel margin Stock to Receiver 3 2. Orange peel on Stock 3	Gun	2. Fore End peeling		:
5. Barrel pitted on side 6. Feed latch fell out 7. Excess wood margin Stock to Receiver, excess steel margin Stock to Receiver 8. Excess wood margin Stock to Receiver 9. Excess steel margin Stock to Receiver 1. Poor finish on grip cap 2. Orange peel on Stock		3. Dirty recoil pad		
6. Feed latch fell out 2 7. Excess wood margin Stock to Receiver, excess steel margin Stock to Receiver 2 8. Excess wood margin Stock to Receiver 2 9. Excess steel margin Stock to Receiver 2 9. Excess steel margin Stock to Receiver 3 1. Poor finish on grip cap 3 2. Orange peel on Stock 3		4. Excess wood margin Sto	ck to Receiver	21
7. Excess wood margin Stock to Receiver, excess steel margin Stock to Receiver 2 8. Excess wood margin Stock to Receiver 2 9. Excess steel margin Stock to Receiver 3 <u>M/700</u> 1. Poor finish on grip cap 3 2. Orange peel on Stock 3		5. Barrel pitted on side		:
excess steel margin Stock to Receiver 2 8. Excess wood margin Stock to Receiver 2 9. Excess steel margin Stock to Receiver 3 <u>M/700</u> 1. Poor finish on grip cap 3 2. Orange peel on Stock 3		6. Feed latch fell out		20
9. Excess steel margin Stock to Receiver]M/7001. Poor finish on grip cap]2. Orange peel on Stock	-	7. Excess wood margin Sto excess steel margin St	ck to Receiver, ock to Receiver	21
M/7001. Poor finish on grip cap12. Orange peel on Stock		8. Excess wood margin Sto	ck to Receiver	28
2. Orange peel on Stock		0 Europe stool moments Ct	ock to Receiver	1:
		9. Excess steel margin St		
Same(3. Finish lifting on grip cap	<u>M/700</u>		p	11
	<u>M/700</u>	1. Poor finish on grip ca	þ	11

•

(over)

CONFIDENTIAL-SUBJECT TO PROTECTIVE ORDER KINZER V. REMINGTON