

MINUTE # 10 - MAY 19, 1982

FROM PAGE NUMBER - 7

SUBJECT: MODEL 700 - BOLT LOCK DELETION

MODEL 700 - BOLT LOCK DELETION

As directed during the October 1981 meeting, the Bolt Lock has been removed from the current production of Model 700's. Since this change is being made without product obsolescence, there will be no trade announcement and the order number remains the same. Letters of notification are being sent to sales personnel and our recommended gunsmiths. Procedures for repair of Model 700's are discussed in F.T. Millener's letter of May 14, 1982. The basic guideline in that letter is to return a gun to the customer with the same features it had when it was sent to Remington.