

RECEIVING AND ESTIMATING REPORT

CUST NO 90859		L2 BLACK TIP ON STOCK	
RECEIVED	DATE ORDERED	DATE CODE	SERIAL NUMBER
7/28/91	08/29/91	KZ 5-75	6854937
MODEL AND GRADE		ORDER	
700 25-06		R 91-17097	
ACCESSORIES		SCOPE BASE L/SIGHTS	
W/STUDS			

DM:

AHLMANS
ROUTE 1 BOX 20
MORRISTOWN
USA

MN 55052

SHIP TO:

AHLMANS
ROUTE 1 BOX 20
MORRISTOWN
USA

MN 55052

INVT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					9-16-91	UPS

UR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
-----------	-----	-----------	-----	-------------	-------

N CONDITION:

☐ NEW☐ SLIGHTLY WORN☐ VERY WORN☐ MISUSED☐ MARRED

TOWER'S REQUEST

Discharges when bolt is closed.

FAULT

Could not duplicate complaint. However, disassembly of rifle revealed upper assembly has been improperly adjusted out of factory - 1) trigger will blow open at 2 pounds, 2) insufficient over travel. Since rifle is loaded with dirt and dust also. Improper maintenance.

Send repair quotation for cleaning and new trigger assembly (if normal cost, as good-will gesture)

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
DE					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6923 REV. 7/90