
From: Nickerson, Ken E.
Sent: Tuesday, July 08, 2008 10:34 AM
To: Supry, Fred L.
Subject: RE: ND Investigation (final)

Fred,

I agree with you. I would also note that the RSO was not within site of all shooters to prevent someone from loading the rifles when someone was down range. They should change the SOP to state no one should be touching there rifles when anyone is down range.

Ken Nickerson, Manager
Field Service Support
Remington Arms Co.
PO Box 700
870 Remington Dr
Madison, NC 27025-0700

(P) 336-548-8783
(F) 336-548-7801

From: Supry, Fred L.
Sent: Tuesday, July 08, 2008 9:31 AM
To: Nickerson, Ken E.
Subject: FW: ND Investigation (final)

Ken,

Read this rather lengthy report. I gave him my opinion that it reads to me that the shooter failed to follow common sense rules (as well as range rules) and accidentally made contact with the trigger.

Fred Supry, Manager
Product Service and Law Enforcement Training
Remington Arms Company
14 Hoefler Avenue
Ilion, NY 13357

Phone: 315-895-3606
Fax: 315-895-3661
e-mail: fred.supry@remington.com

From: Johnson, Rick W.
Sent: Tuesday, July 08, 2008 8:55 AM
To: Supry, Fred L.
Subject: FW: ND Investigation (final)

Please read thru and give me your comments please sir?

Rick W. Johnson, Sales Manager
Remington Law Enforcement Division
(501) 259-4300 (Cell)
(501) 676-4208 (Office)

From: Craig Baltzer [mailto:cbaltzer@deltapolice.ca]
Sent: Tuesday, July 08, 2008 1:47 AM
To: Mark Cockman; Johnson, Rick W.
Subject: FW: ND Investigation (final)

hey read this crock of a report, can you say finger on the trigger

wasn't it pre 1976 Model 700 rifles that had to have the safety off to move the bolt?

Cst. Craig Baltzer, Firearms Section

office 604-946-4411 ext. 5134

pager 604-320-9744

Delta Police Dept.
4455 Clarence Taylor Cr.
Delta, BC, Canada V4K3E1