BARBER - RE 0000078

From: Nickerson, Ken E.

Sent: Monday, May 19, 2008 11:19 AM

To: Curtis, Danny Subject: RE: 700 sniper rifle

I contacted Scott in a separate email but this is to be sent back to the factory. I bet the trigger was adjusted incorrectly and causing the malfunction. This is the cause 99% of the time for you info.

Thanks,

Ken

From: Curtis, Danny

Sent: Monday, May 12, 2008 1:33 PM

To: Scott Little **Cc:** Nickerson, Ken E. **Subject:** RE: 700 sniper rifle

Scott, I am forwarding your info to Ken Nickerson at Remington's main office. He will tell us both the procedure to correct the problems. Thanks, Dan

Dan Curtis
Remington Arms Company, Inc.
Bushmaster Firearms International
Law Enforcement Division
Regional Business Development Manager
Western Region
Cell (801) 376-4510
Office (801) 768-9333
Fax (801) 341-5959
Visit our LE websites:
www.remingtonle.com
www.bushmaster.com

From: Scott Little [mailto:LITTLES@bouldercolorado.gov]

Sent: Monday, May 12, 2008 11:12 AM

To: Curtis, Danny **Subject:** 700 sniper rifle

Dan,

We have a .308 700 that is malfunctioning. When the safety is in the fire position the firing pin moves forward while doing rapid bolt manipulation drills. I was able to recreate the problem in the shop. I sonic cleaned the bolt and trigger group and blew it out with compressed air, lubricated it and reassembled it (rifle not the trigger group) and

1

BARBER - RE 0000079

it still would repeat this malfunction. Do I need a service authorization number? Who what and where do I send the rifle

The rifle was used on March 17 2008 in a deadly force deployment and it performed correctly. This malfunction was detected at a training shoot early this month.

Ofc. Scott Little (Armorer) 1805 33rd Street Boulder Colorado 80301 303-441-3477