

GENERAL - contd.

BLACK OXIDE - contd.

1959 - middle of 1962 - Use of DuPont cement on threads prior to assembly.

Mid-1962 - middle of 1963 - Cement changed to use of adiprene.

Mid-1963 to date - Changed to polyurethane caulk.

Every effort is being made to follow the present practice, correctly applying polyurethane caulk to all joints before assembly on Model 600 and 700 Barrels and Receivers, and Models 742-760 Barrels and Barrel Extensions.

Inspection of warehouse guns indicates that with the present process, only occasional minor evidence of bleedout has been noted.

Sales reported that while there are few written complaints, the problem of bleedout has been noted by the field force in viewing Remington guns on dealer's shelves.

Committee Action

The Ilion plant is to continue work on the bleedout problem.

GUN WARRANTY

Production stated that Remington could equal any gun warranty being offered by competitors. It is believed that the Browning gun warranty does not essentially offer more than the Remington warranty. Due, however, to the Browning phrasing, it might appear to do so.

Committee Action

Sales and Production will review the Remington gun warranty phrasing.