83 83

## QUALITY REVIEW AT ILION - contd.

## Review of Quality Performance and Progress in Past 12 Months - contd.

Model 1100 - Three were "Fail to feed from Magazine." A change in Hammer design corrected a major cause of this malfunction. There was one each of these malfunctions. "Ejector shot off"; "Extractor drops shell"; "Double feed".

Model 552 - One "Doesn't blow back"; one "Fails to connect"; one "Fails to eject".

Model 742 - One "Broken Extractor claw" ; one "Port Cover jumped rail"; one "Doesn't blow back", - 243 caliber. . 1993 - 1994 1994 - 1994

Model 788 - One "Safety won't work" - new design, lever bound in Receiver clearance cut "Extractor drops shell".

F. Gratis Repairs

Exhibit 13 shows that gratis repairs are about the same percentage of guins shipped as they have been for the last ten years except for the Model 3200 which includes guns returned for modification.

G. Product Improvements Pregram - Exhibit 14. Warehouse Audit

A Wane ouse audit was made on September 16, 1975. H. D. Albaugh selected at random from the warehouse five each of the Model 3200, 1100 and 700 guns. These guns were inspected by Mr. Albaugh, then Subjected to the standard Finished Gun Audit; results are reported in Exhibit 15. Mr. Albaugh's observations are in Exhibit 16.

These guns were reviewed at the close of the Operations Committee Meeting. The reports were not reviewed at the meeting.

WIL02981