BARBER - Kinzer PPS GAL RE0001810

REMINGTON ARMS COMPANY, INC.



SPORTING FREARMS
TRAPS
POWDER METAL PARTS
IUON, NEW YORK
AMMUNITION, BRIDGEPORT, CONNECTICUT
LONGKE, ARKANSAS

MANUFACTURERS OF
SPORTING FIREARMS. AMMUNITION
TRAPS TARGETS
ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

PETERS CARTRIDGE DIVISION BRIDGEPORT, CONNECTICUT TARGETS, ADA, OKLAHOMA ATHENS, GEORGIA FINDLAY, OHIO CABLE—HARTLEY, BRIDGEPORT

September 14, 1984

Mr. Dixon H. Fotheringham 667 N. 1050 W.

St. George, Utah 84770

Dear Mr. Fotheringham:

Your letter of August 21, 1984 that was addressed to our Bridgeport, Connecticut facility, regarding the accidental firings you have experienced while releasing the safeties on two (2) Model 700 rifles that you own, has been forwarded to this office for handling.

We were indeed sorry to learn of your having a problem of this nature, as it is not characteristic of the Model 700 rifle.

Generally, the type of malfunction you described results from either improper adjustment of the trigger assembly outside our factory, from improper maintenance of the rifle, or, from pressure being inadvertently applied to the trigger at the instant the safety is released.

Please, at your convenience, return the rifles via insured and collect transportation, to:

Remington Arms Company, Inc. Attn: Mr. J.A. Stekl Supervisor Product Service Ilion, New York 13357

Upon receipt, we will thoroughly examine the firearm and, if they are found to be factory faulty, any necessary repairs will be made on a no-charge basis.

Thank you for bringing this matter to our attention and for having afforded us this opportunity to be of service to you.

Sincerely,

J.A. Stekl, Supervisor

Product Service

JAS:tpp