


-2-

after the rifle left our factory, as the sealant on the screws was not original. In the future, we strongly advise that the trigger not be adjusted by untrained non-Remington personnel.

Since we found the trigger assembly to have been tampered with and outside of our specifications, we can either properly re-adjust the present assembly or, if it will better restore confidence in the rifle, we will install a new trigger assembly at no-charge as a gesture of good-will (either option is subject to a \$10.00 handling plus return shipping charge). We will await the decision and reply.

Thank you for affording us the opportunity to examine the rifle and report our findings.

Sincerely,



J.A. Stekl, Specialist
Product Service

JAS:tpp