

ORDER
92-17862

FROM:		SHIP TO:	
HURLEY, LARRY		HURLEY, LARRY	
PO BOX 932		PO BOX 932	
CLINTON	TN 37717	CLINTON	TN 37717

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	Rifle sometimes fires when safety is released also, sometimes when bolt is closed					F1
BOLT ASSY.						F2
BARREL ASSY.						F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

Cannot duplicate either of these complaints after many attempts. However, it was noted that rust is present on the bottom side of the trigger and on the connector. Also, the trigger operation is somewhat slow, possibly because of this rusted condition.

Trigger pull 3½ pounds; rear-lift .013"

[illegible]

RD6925 REV. 1/