ienced. In future use, we strongly advise that oil be used sparingly and not let accumulate in or on the trigger assembly, and that the trigger assembly not be adjusted by untrained non-Remington personnel, as both of these conditions could adversely affect the operation of the trigger assembly.

Mr. Lannoye, as a gesture of good-will, we will install a new trigger assembly at no-charge, to restore your confidence in the rifle.

Thank you for having afforded us the opportunity to be of service and trust that our handling meets with your approval.

Sincerely,

Product Service

DJS:tpp

٣

Remington Arms Company, Inc.

• • •