


removal of the barrel action from the stock assembly revealed that the trigger assembly contained an excessive amount of lubrication on both inside and outside. We strongly advise that oil be used sparingly on the firearm and not let accumulate in or on the trigger assembly as this condition could adversely affect the operation of the trigger assembly.

Since we found the firearm to be completely correct and function normally in every respect, we are prepared to return it to you, however, we will install a new trigger assembly as a gesture of good-will, before we effect its return.

Thank you for affording us the opportunity to examine the rifle and report our findings.

Mr. Booth, the above adjustment is at no charge.

Sincerely,

A handwritten signature in cursive script, appearing to read "J.A. Stekl".

J.A. Stekl, Specialist
Product Services

JAS:tp

Remington Arms Company, Inc.